



**SUMMARY**  
1234 Main St. Steamboat Springs CO  
80487  
Buyer Name  
01/10/2019 9:00AM

Brian Hickory  
InterNACHI Certified Home Inspector  
Hickory Property Services LLC  
970-367-7255  
brian@hickoryproperty.com



These summary pages are not the entire report. The complete report may include additional information of interest or concern to you. It is strongly recommended that you promptly read the complete report.

**Congratulations on buying your new home and THANK YOU for choosing Hickory Property Services to perform your home inspection!**

### 2.1.1 Coverings


#### ICE DAMS




Ice dams have formed on the West and East side of the roof. An ice dam is a ridge of ice that forms at the edge of a roof and prevents melting snow from draining. As water backs up behind the dam, it can leak through the roof and cause damage to walls, ceilings, insulation and other areas. Ice dams are formed by an interaction between snow cover, outside temperatures, and heat lost through the roof. Specifically, there must be snow on the roof, warm portions of the upper roof (warmer than 32 F), and cold portions of the lower roof (at freezing or below). Melted snow from the warmer areas will refreeze when it flows down to the colder portions, forming an ice dam. To prevent the ice dams from forming, there are various approaches to take such as adding insulation in the attic, seal air leaks at plumbing pipes & electrical penetrations in attic and adding vents. Recommend a qualified roofing contractor evaluate to determine the best approach to take to prevent this from occurring each winter.

#### Recommendation

Contact a qualified roofing professional.





### 2.3.1 Flashings


#### STEP FLASHING MISSING

Recommendation

Step flashing is not installed at the sidewalls and chimney chase; instead just the underlayment is installed. Anywhere roof sections adjoin wall sections, step flashing should be used to keep water from entering the walls. The step flashing should be extended at least 4 inches up the wall from the roof deck and at least 4 inches out along the roof deck (2015 International Residential Code [IRC]) with the house siding installed over the step flashing, ending at least 1 inch above the roof surface. Recommend a qualified roofing contractor install step flashing to prevent water damage to the structure.

#### Recommendation

Contact a qualified roofing professional.



### 2.4.1 Skylights, Chimneys & Other Roof Penetrations

#### INPROPER FLASHING AT ROOF PENETRATION

Recommendation

There is no counter flashing installed at the chimney roof penetration. The point at which the chimney penetrates the roof should be sealed with flashing to prevent leaks and moisture damage. Recommend a roofing contractor install counter flashing.

Recommendation

Contact a qualified roofing professional.



### 3.1.1 Siding, Flashing & Trim

## GROUND CLEARANCE

 Recommendation

NORTHEAST

Inadequate clearance between siding and ground on the NE corner of the house. Recommend a minimum ground clearance between bottom of siding and ground of 4". Siding in contact with the ground or soil is a serious concern because that condition can provide direct access for wood destroying insects.



### 3.1.3 Siding, Flashing & Trim

#### **SIDING PAINT/ FINISH FAILING**

 Recommendation

The paint or finish is failing on the siding at places, primarily on the East side of the home. This can lead to deterioration and rot of the material. Recommend that the areas be properly prepared and painted / finished.

#### Recommendation

Contact a qualified painter.



### 3.4.1 Decks, Balconies, Porches & Steps

#### **WEATHERED DECKING BOARDS**

 Recommendation

The subflooring on the deck is weathered and showing signs of moisture damage on the East side of the deck. The deck had a membrane installed to keep the underside of the deck waterproof, but these moisture stains indicate the membrane may be compromised and a repair of the membrane could be needed to keep the underside of the deck fully waterproof. I would recommend having a deck contractor evaluate the deck to determine if the membrane needs to be repaired and what the cost would be.

Recommendation  
Contact a qualified professional.



### 3.4.2 Decks, Balconies, Porches & Steps

#### LEDGER BOARD IMPROPERLY INSTALLED


 Recommendation

Ledger boards for one or more decks, balconies or porches appeared to be attached with nails only. This method of attachment is substandard and may result in such structures separating from the main building. This is a potential safety hazard. Modern standards call for ledger boards to be installed with 1/2 inch lag screws or bolts into solid backing, and brackets such as [Simpson Strong Tie DTT2 brackets and threaded rod](#), connecting interior and exterior joists. Recommend that a qualified contractor repair per standard building practices. For more information, visit:

[Ledger Boards](#)

[Safe Decks](#)

Recommendation  
Contact a qualified deck contractor.



3.4.3 Decks, Balconies, Porches & Steps

 Recommendation

**RAILING UNSAFE**

There is an unsafe opening in the railing. The spacing on the rail should not exceed 4". An opening greater than 4" is a serious safety hazard especially for children as their head or other body part can become trapped.

Recommendation  
Contact a qualified deck contractor.



3.4.4 Decks, Balconies, Porches & Steps

 Recommendation

**MISSING POST BEAM TIES**

On the a east side of the deck, the rim joist was not positively secured with hangers or supported with a post. Deck beams are commonly connected to support posts by "toenailing," which is inadequate. Decks are subject to movement under live loads and require a positive connection between their support posts and beams. Recommend that a qualified contractor repair per standard building practices. For example, by installing metal plates, plywood gussets or dimensional lumber to connect posts and beams.

Recommendation  
Contact a qualified professional.




3.5.1 Eaves, Soffits & Fascia

 Recommendation

**HOLES IN SOFFIT**

There were a couple of holes in the soffit on the South side of the house which should caulked. This can allow water intrusion and rodent infestation as well as deterioration of the surrounding material.



### 3.6.1 Vegetation, Grading, Drainage & Retaining Walls

#### **NEGATIVE GRADING**



Grading is sloping towards the home in some areas. This can result in water accumulating around building foundations or underneath buildings. At a minimum, monitor these areas, and areas under the structure in the future for accumulated water. If water does accumulate, recommend grading soil so it slopes down and away from buildings with a slope of at least 1 inch per horizontal foot for at least 6 feet out from buildings.

[Here is a helpful article](#) discussing negative grading.



### 4.1.1 Foundation

#### **FOUNDATION CRACKS - MINOR**



A minor diagonal crack was noted at the foundation wall on the South side. The crack is larger on top and reduces to a hairline crack as it continues down the wall of the foundation. This type of crack indicates there is some slight settling or it is a shrinkage crack when the concrete was curing and has grown over time. This part of the foundation wall is the only section that is not backfilled which may be why it has settled. The rest of the concrete foundation did not have any cracks and appears to be in great shape. Recommend monitoring this one diagonal crack for more serious shifting/displacement overtime.

[Here is an informational article](#) on foundation cracks.

Recommendation

Recommend monitoring.



#### 4.2.1 Crawlspace & Basements

##### **NO VAPOR BARRIER**

 Recommendation

There is no vapor barrier beneath the flooring in places. This can result in unwanted moisture.



#### 4.3.1 Floor Structure

##### **MOLD**

 Recommendation

Observed signs of a white powder on the floor joist and subflooring on the west side of the crawl space. The white powder is most likely a mold or fungus growth due to high humidity or condensation in the crawl space. The moisture meter did not indicate any water was present in the joists or subflooring, but overtime the mold/fungus could cause damage to the wood. A vapor barrier has been installed in places in the crawl space, though it does not cover the whole area and is torn in places. A structural engineer could provide repair requirements along with preventive solutions for this problem.

Recommendation

Contact a qualified structural engineer.





#### 4.3.2 Floor Structure

### SILL PLATE NOT SECURED TO FOUNDATION

Recommendation

The sill plate is not secured to the foundation. I checked along the perimeter in various locations and could not find an anchor bolt or nuts. Recommend repair for proper attachment to the foundation.

Recommendation  
Contact your builder.



#### 7.2.1 Hot Water Systems, Controls, Flues & Vents

### NO DRIP PAN

Recommendation

No drip pan was present. Recommend installation by a qualified plumber.



### IMPROPER P-TRAP INSTALLATION

In the crawl space, a "running trap" has been installed which is considered an improper p-trap. A running trap is when a drain line from a fixture runs horizontal then makes a u-shape trap and continues horizontal. It lowers the velocity and turbulence needed to wash (clean/scour) the trap, and causes slow running drains, among other things. The p-trap should be installed at the vertical tailpiece of the fixture.

In the bathrooms, a flexible drain transition pipe is installed. This is not approved by plumbing code because the inside walls are not smooth and will hold gunk. This kind of pipe is thinner and prone to leakage.

Recommendation

Contact a qualified plumbing contractor.



### TOILET LOOSE


BATHROOM, SOUTH BATHROOM

The toilet is not well secured to the floor. Recommend repair to help prevent (further) leaks around the wax ring.

Recommendation  
Contact a qualified professional.



Loose toilet



© Carson Dunlop

### 7.6.2 Fixtures


## LEAKING SUPPLY LINES

MASTER BATHROOM

Recommendation

The water shut-off valve at the toilet leaks. It has to be turned a quarter of the way open for it to not leak. Otherwise it leaks fully opened or any one it is turned. A qualified plumber should repair as necessary.

Recommendation  
Contact a qualified plumbing contractor.



### 7.7.1 Tubs, Shower and Tile

## CAULKING DETERIORATED/ MISSING

MASTER BATHROOM

Recommendation

The caulking around the tub is missing or worn. Water can penetrate these areas and cause damage. Recommend repair to help protect from moisture damage.

Recommendation  
Contact a handyman or DIY project



### 7.7.3 Tubs, Shower and Tile

#### **GROUT - GAPS AND CRACKS**

 Recommendation

There are cracks and gaps in the grout. Recommend repair to help prevent water damage.

Recommendation

Contact a qualified tile contractor



### 8.2.1 Attic Insulation

#### **IMPROPER INSTALLATION**

 Recommendation

Attic insulation was too close to the roof sheathing in places along the perimeter of the roof. There should be a minimum of a 1 - 2" gap between the insulation and roof sheathing to allow for proper ventilation. This could be one of the causes for the ice dam build up on the roof. Recommend a qualified insulation contractor evaluate and correct.

Recommendation

Contact a qualified insulation contractor.



### 8.3.1 Exhaust Systems

#### **BATHROOM VENTS INTO ATTIC**

 Recommendation

The flex duct for the vent from the bathroom is disconnected in the attic and vents into the attic, which can cause moisture and mold. Recommend the vent be repaired so it can properly exhaust to the exterior.

#### Recommendation

Contact a qualified HVAC professional.



### 8.3.2 Exhaust Systems

#### **NO EXHAUST FAN IN BATHROOM**


 Recommendation

#### HALLWAY BATHROOM

The bathroom does not have an exhaust fan installed. An exhaust fan is recommended to prevent moisture and humidity buildup in the bathroom that will cause damage to walls and ceiling over time.

#### Recommendation

Contact a qualified HVAC professional.



### 9.3.1 Floors

#### **DAMAGED (GENERAL)**


The vinyl wood floors in the hallway had general moderate damage visible at the time of the inspection. Recommend repair by a qualified contractor.

Recommendation

Contact a qualified flooring contractor



Recommendation



### 9.4.1 Walls




#### **POOR PATCHING**

LIVING ROOM

Sub-standard drywall patching observed at time of inspection. Recommend re-patching.



Recommendation



9.4.2 Walls

**POOR PAINT APPLICATION**


BEDROOMS, BACK DECK ENTRY AREA



The wall does not have an even coat of paint in their spots where the paint is thin or was not applied properly. Recommend repainting the wall.

Recommendation

Contact a qualified painter.





### 9.5.1 Ceilings


## POOR PAINT APPLICATION

### MASTER BEDROOM

The ceiling does not have an even coat of paint in their spots where the paint is then or was not applied. Recommend repainting ceiling.

#### Recommendation

Contact a qualified painter.



### 9.5.2 Ceilings

## POOR TAPING

### BEDROOMS

The drywall joints on the ceiling were not taped properly and can be seen. If desired to repair recommend a drywall contractor to re-tape and finish.





Recommendation  
Contact a qualified drywall contractor.



#### 9.7.1 Countertops & Cabinets

### COUNTERTOP CRACKED/CHIPPED


 Recommendation

Countertop had one or more cracks or chips. Recommend qualified countertop contractor evaluate and repair.

[Here is a helpful article](#) on repairing cracks, chips & fissures.

Recommendation

Contact a qualified countertop contractor.



#### 9.7.2 Countertops & Cabinets


### COUNTERTOP NOT SECURED

 Recommendation

Kitchen countertop was not secured to the wall or cabinet. Recommend qualified countertop contractor secure countertop properly.

Recommendation

Contact a qualified countertop contractor.



9.7.3 Countertops & Cabinets  
**GROUT DETERIORATING**

 Recommendation

MASTER BATHROOM

Grout lines were cracked or severely deteriorated. Recommend a qualified contractor repair or replace grout.

Recommendation  
Contact a qualified countertop contractor.



12.2.2 Main & Subpanels, Service & Grounding,  
Main Overcurrent Device

 Recommendation

**POINTED SCREWS IN ELECTRICAL  
PANEL**

The panel cover was removed in order to inspect and test the internal components. Two pointed screws were removed from the panel cover. This is a potentially dangerous condition. If one of the screws penetrates the insulation of a wire, a direct short will occur at a minimum popping a breaker or possibly electrocuting someone. Recommend replacing with a flat head tip screw rated for electrical panels.

Recommendation  
Contact a qualified electrical contractor.




12.3.1 Branch Wiring Circuits, Breakers & Fuses

 Recommendation

**ALUMINUM BRANCH CIRCUITS**

Aluminum wire appears to be installed on a couple of the branch electrical circuits. These single strand, branch circuit aluminum wires were used widely in houses during the mid 1960s and 1970s. According to the U.S. Consumer Product Safety Commission, problems due to expansion can cause overheating at connections between the wire and devices (switches and outlets) or at splices, which has resulted in fires. For further information on aluminum wiring contact the U.S. Consumer Product Safety Commission via the Internet at <http://www.cpsc.gov/> . It is recommended that the electrical system be evaluated by a licensed electrician.



12.3.2 Branch Wiring Circuits, Breakers & Fuses

 Recommendation

**BARE WIRE NOT TERMINATED**

CRAWLSPACE

Bare wire ends, or wires with a substandard termination, were found at one or more locations. This is a potential shock hazard. Recommend that a qualified electrician repair as necessary. For example, by cutting wires to length and terminating with wire nuts in a permanently mounted, covered junction box.

Recommendation  
Contact a qualified professional.




12.4.1 Lighting Fixtures, Switches & Receptacles

 Recommendation

**LIGHT INOPERABLE**

BACK DECK ENTRY

One or more lights are not operating. New light bulb possibly needed.



12.4.2 Lighting Fixtures, Switches & Receptacles

**SWITCHES INSTALLED IMPROPERLY**

MASTER BEDROOM, NORTHEAST BEDROOM, LOFT

 Recommendation

One or more receptacles are loose and not well secured. Recommend licensed electrician repair or replace.



12.6.1 Smoke Detectors

**NO SMOKE DETECTORS INSTALLED**

 Immediate Action Recommended

**\*Safety\*** Inspector recommends installing a smoke detector to provide improved fire protection for home.

Generally-accepted current safety standards recommend smoke detectors be installed in the following locations:

- In the immediate vicinity of the bedrooms
- In all bedrooms
- In each story of a dwelling unit, including basements and cellars, but not including crawl spaces and uninhabitable attics.
- In residential units of 1,200 square feet or more, automatic fire detectors, in the form of smoke detectors shall be provided for each 1,200 square feet of area or part thereof.
- Any smoke detector located within 20 feet of a kitchen or bedroom containing a tub or shower must be a photoelectric type.

Recommendation

Contact a handyman or DIY project

---