



SUMMARY
1234 Main St. Waterford Works New
Jersey 08089
Buyer Name
01/13/2019 9:00AM

Todd Vazquez
NJ Home Inspector License #...
Smart Inspections LLC
(609) 805-0641
todd@smart-inspections.com



INTRODUCTION

We appreciate the opportunity to conduct this inspection for you! Please carefully read your entire Inspection Report. Call us after you have reviewed your report so we can go over any questions you may have. Remember, when the inspection is completed and the report is delivered, we are still available to you for any questions you may have throughout the entire closing process.

Properties being inspected do not "Pass" or "Fail." The following report is based on an inspection of the visible portion of the dwelling; the inspection may be limited by vegetation and possessions. This report will focus on safety and function, not current building code. This report identifies specific non-code, non-cosmetic concerns that the inspector feels may need further investigation or repair.

For your safety and liability purposes, we recommend that licensed contractors evaluate and repair any critical concerns and defects. Note that this report reflects observation made at the time of the inspection and is not a forecast of future conditions. We recommend that you or your representative carry out a final walk-through inspection immediately before closing to check the condition of the property, using this report as a guide.

PURPOSE AND SCOPE

This document was prepared as a report of visual defects noted at the time and date of the inspection. It is not necessarily an all-inclusive summary, as additional testing or inspection information/processes and analysis may be pending. It is non-transferable and subject to all terms and conditions specified in the Pre-Inspection Agreement. It should be noted that a standard pre-purchase inspection is a visual assessment of the condition of the structure at the time of inspection and is subject to day-to-day changes.

The inspection and inspection report are offered as an opinion only, of items observed on the day of the inspection. Although every reasonable effort is made to discover and correctly interpret indications of previous or ongoing defects that may be present, it must be understood that no guarantee is expressed nor implied nor responsibility assumed by the inspector or inspection company for the actual condition of the building or property being examined.

This company "Smart Inspections, LLC" endeavors to perform all inspections in substantial compliance with the State of New Jersey Standards of Practice for Home Inspectors N.J.A.C. 13:40-15.15. The scope of the inspection is outlined in the Pre-Inspection Agreement, agreed to and signed by the Client. Our inspectors inspect the readily accessible and installed

components and systems of a property as follows: This report contains observations of those systems and components that are, in the professional opinion of the inspector authoring this report, significantly deficient in the areas of safety or function. When systems or components designated for inspection in the Standards are present but are not inspected, the reason the item was not inspected may be reported as well. This report summarizes our inspection conducted on this date at the above address.

EXCLUSIONS AND LIMITATIONS

The client should understand that this report is the assessment of a Property Inspection Consultant, not a professional engineer, and that, despite all efforts, there is no way we can provide any guarantee that the foundation, structure, and structural elements of the unit are sound. We suggest that if the client is at all uncomfortable with this condition or our assessment, a professional engineer be consulted to independently evaluate the condition, prior to making a final purchase decision.

This inspection is limited to any structure, exterior, landscape, roof, plumbing, electrical, heating, foundation, bathrooms, kitchen, bedrooms, hallway, and attic sections of the structure as requested, where sections are clearly accessible, and where components are clearly visible. Inspection of these components is limited and is also affected by the conditions apparent at the time of the inspection and, which may, in the sole opinion of the inspector, be hazardous to examine for reasons of personal or property safety.

This inspection will exclude insulation ratings, hazardous materials, retaining walls, hidden defects, buried tanks of any type, areas not accessible or viewable, and all items as described in the Pre-Inspection Agreement. As all buildings contain some level of mold, inspecting for the presence of mold on surfaces and in the air is not a part of the actual inspection, but is a value-added service to help you, the client, minimize the risks and liabilities associated with Indoor Air Quality.

The New Jersey Standards of Practice for Inspecting Residential Properties are applicable to all residential properties in the State of New Jersey. They are not technically exhaustive and do not identify concealed conditions or latent defects.

Inspectors are not required to determine the condition of any system or component that is not readily accessible; the remaining service life of any system or component; determination of correct sizing of any system or component; the strength, adequacy, effectiveness or efficiency of any system or component; causes of any condition or deficiency; methods, materials or cost of corrections; future conditions including but not limited to failure of systems and components; the suitability of the property for any specialized use; compliance with regulatory codes, regulations, laws or ordinances; the market value of the property or its marketability; the advisability of the purchase of the property; the presence of potentially hazardous plants or animals including but not limited to wood destroying organisms or diseases harmful to humans; mold; mildew; the presence of any environmental hazards including but not limited to toxins, carcinogens, noise, and contaminants in soil, water or air; the effectiveness of any system installed or methods utilized to control or remove suspected

hazardous substances; the operating costs of any systems or components and the acoustical properties of any systems or components.

Inspectors are not required to operate any system or component that is shut down or otherwise inoperable; any system or component which does not respond to normal operating controls or any shut off valves or switches.

Inspectors are not required to enter into or onto any area or surface, or perform any procedure or operation which will, in the sole opinion of the inspector, likely be dangerous to the inspector or others or damage the property, its systems or components; nor are they required to move suspended ceiling tiles, personal property, furniture, equipment, plants, soil, snow, ice or debris or dismantle any system or component, or venture into confined spaces.

Our inspectors are not required to enter crawlspaces or attics that are not readily accessible nor any area which has less than 24" by 30" of clearance or a permanently installed walkway or which will, in the sole opinion of the inspector, likely to be dangerous, inaccessible, or partially inaccessible to the inspector or other persons, or where entry could possibly cause damage to the property or its systems or components.

2.1.1 Foundation Walls

EXTERIOR FOUNDATION - SHRINKAGE CRACKS

[BACK](#)

The foundation wall exhibited signs of shrinkage cracking. Shrinkage cracks appear as part of the natural concrete curing process and are not a structural concern. The inspector recommends monitoring the cracks for future displacement or shifting by a qualified professional.

Recommendation

Contact a foundation contractor.

 Recommendation



2.2.2 Exterior Cladding


SIDING PENETRATION

The siding had one or more wall penetrations that were not sealed properly. This condition may allow moisture intrusion, which may cause damage to surrounding components. The inspector recommends that all wall penetrations be properly sealed by a qualified professional.

Recommendation

Contact a qualified siding specialist.

 Recommendation



2.4.1 Trim and Flashing

TRIM - MISSING

 Recommendation

A section of the rack board trim is missing. This condition may allow moisture intrusion to damage surrounding components. The inspector recommends further evaluation and repair of the trim by a qualified professional.

Recommendation

Contact a qualified siding specialist.



2.8.1 Chimney Exterior

CHIMNEY CROWN - MINOR CORROSION

 Recommendation

The chimney crown exhibited signs of corrosion. This condition may allow moisture intrusion, which may cause damage to surrounding components. The inspector recommends further evaluation and repair of the chimney crown by a qualified professional.

Recommendation

Contact a qualified chimney contractor.



2.9.1 Decks, Patios and Porches

PORCH - ROOF SUPPORT POST

 Recommendation

One or more porch roof support posts exhibited signs of wood rot. This condition is likely caused by moisture intrusion and will only worsen over time. The inspector recommends further evaluation and repair of the damaged posts by a qualified professional.

Recommendation

Contact a qualified carpenter.



2.9.2 Decks, Patios and Porches

PORCH - EVIDENCE OF PAST REPAIR

 Recommendation

The front porch exhibited signs of past repair, likely from settlement. Additional settlement may cause the mortar joints to deteriorate. The inspector recommends the affected areas be monitored for further settlement or separation of mortar joints by a qualified professional.

Recommendation
Contact a qualified concrete contractor.



2.9.3 Decks, Patios and Porches

PORCH - MINOR CRACK

 Recommendation

The porch had one or more minor cracks. This condition may allow moisture intrusion and cause additional damage to the concrete porch. The inspector recommends the cracks be further evaluated and repaired by a qualified professional.

Recommendation
Contact a qualified concrete contractor.



2.10.1 Walkways, Steps and Railings

WALKWAY - CRACKING

 Recommendation

FRONT

One or more sections of the concrete walkway were cracked. This condition may allow moisture intrusion, which could cause upheaval. The inspector recommends further evaluation and repair by a qualified professional.

Recommendation
Contact a qualified concrete contractor.



2.10.2 Walkways, Steps and Railings

RAILING - NOT ATTACHED

FRONT



The front stairway railing was not attached to its support post. This condition may cause a safety hazard for anyone who may use the railing for support. The inspector recommends further evaluation and repair by a qualified professional.

Recommendation
Contact a qualified carpenter.



2.10.3 Walkways, Steps and Railings

RAILING - WOOD ROT

FRONT



The front railing exhibited signs of wood rot in one or more locations. This condition may cause structural failure of the railings. The inspector recommends further evaluation and repair by a qualified professional.

Recommendation
Contact a qualified carpenter.



2.12.1 Landscaping and Retaining Walls

RETAINING WALL - DETERIORATION

BACK



One or more retaining walls are exhibiting signs of deterioration. This condition may cause the retaining walls to fail when under additional loads. The inspector recommends further evaluation and repair of the retaining walls by a qualified professional.

Recommendation
Contact a qualified professional.



2.12.2 Landscaping and Retaining Walls

VEGETATION NEXT TO STRUCTURE

 Recommendation

LEFT SIDE

Decorative vegetation is either too close or touching the siding or foundation. Vegetation too close to the structure can lead to excess moisture around the soil and foundation. The inspector recommends that all vegetation be cut back or removed by a qualified handyman or contractor. There should be a minimum of a two foot buffer between the structure and vegetation.



Recommendation
Contact a qualified professional.

3.1.1 Roof Surface

AGING ASPHALT SHINGLES

 Recommendation

Although functional, standard three tab roof shingles had widening gaps between tabs and missing granules, which indicate they are near the end of their functional life expectancy. The shingles are likely original to the structure, approx. 17 years old. The life expectancy of three tab shingles is about 20 years. Continued use of the shingles without replacement may lead to moisture penetration into the interior space. The inspector recommends further evaluation of the asphalt shingles by a qualified professional.



Recommendation
Contact a qualified roofing professional.

3.2.1 Roof Drainage Systems

DOWNSPOUT DRAIN NEAR DWELLING

Recommendation

BACK

One or more downspouts drain too close to the home's foundation. This can result in excessive moisture in the soil at the foundation, which can lead to foundation/structural movement. The inspector recommends a qualified contractor adjust downspout extensions to drain at least 6 feet from the foundation.

Recommendation
Contact a qualified gutter contractor



3.2.2 Roof Drainage Systems

DOWNSPOUT EXTENSION - CRUSHED

Recommendation

BACK

One or more downspout extension pipes were crushed. This condition may cause water to back up, causing the roof drainage system to fail. The inspector recommends further evaluation and repair of the entire roof drainage system by a qualified professional.

Recommendation
Contact a qualified gutter contractor




3.2.3 Roof Drainage Systems

GUTTER - LOOSE GRANULES

Recommendation

One or more gutters exhibited signs of containing loose shingle granules. This condition is characteristic of an aging roof. The granules should be cleaned from the gutters so they don't impede the flow of water runoff. The inspector recommends further evaluation and repair by a qualified professional.

Recommendation
Contact a qualified roofing professional.



3.3.1 Roof Flashings

ROOF PENETRATION - EXPOSED FLASHING FASTENERS

Recommendation

One or more vent flashing fasteners were exposed to environmental elements. This condition may cause fastener corrosion, which could cause moisture intrusion. The inspector recommends evaluation and repair of all of the roof penetration flashings by a qualified professional.

Recommendation
Contact a qualified roofing professional.



3.3.2 Roof Flashings

CHIMNEY FLASHING - SILICON/COUNTER FLASHING

Recommendation

The joint around the chimney is sealed with silicon. Silicon is not the preferred method for sealing the connection between the siding and chimney. This condition is likely an attempt to stop moisture intrusion that has caused damage to the roof structure over the garage. The inspector recommends further evaluation and repair of the affected areas by a qualified professional.

Recommendation
Contact a qualified roofing professional.



4.1.1 Roof Structure

ROOF SHEATHING - MOISTURE INTRUSION

Recommendation

ABOVE GARAGE

At the time of the inspection, one or more sections of the roof sheathing exhibited signs of moisture intrusion. This condition, if it has not already been repaired, may lead to the growth of mold and/or water damage to surrounding components. The inspector recommends further evaluation of the roof sheathing by a qualified professional.

Recommendation
Contact a qualified roofing professional.



5.1.1 Windows

INOPERABLE WINDOW

1ST FLOOR FRONT

One or more of the windows at the time of the inspection were not operational. Inoperable windows may prevent egress during emergency situations. The inspector recommends that all of the windows be evaluated and repaired by a qualified professional.

Recommendation

Contact a qualified window repair/installation contractor.



5.1.2 Windows

WINDOW - DAMAGED SEALANT

One or more windows exhibited signs of damaged sealant. This condition may compromise the thermal efficiency of the windows. The inspector recommends further evaluation and repair by a qualified professional.

Recommendation

Contact a qualified window repair/installation contractor.



5.5.1 Walls

DRYWALL - POOR PATCHING

1ST FLOOR BATHROOM

One or more sections of dry patching was sub-standard. This condition is an indication of poor workmanship, likely not done by a qualified professional. The inspector recommends the drywall be re-patched using proper techniques by a qualified professional.

Recommendation

Contact a qualified drywall contractor.



6.6.1 Lighting Fixtures, Switches & Receptacles

RECEPTACLE - COVER PLATES DAMAGED


BASEMENT

One or more switch plate covers are damaged. This condition may cause a shock hazard. The inspector recommends further evaluation and repair by a qualified professional.

Recommendation

Contact a qualified electrical contractor.

 Safety Hazard



6.6.2 Lighting Fixtures, Switches & Receptacles

RECEPTACLE - MISSING COVER PLATE

One or more receptacle cover plates were missing. This condition may cause an electrical short or shock hazard. The inspector recommends evaluation and repair of all cover plates by a qualified professional.

Recommendation

Contact a qualified electrical contractor.

 Recommendation



7.4.1 Fixtures and Faucets

TOILET - FAILING WAX SEAL


1ST FLOOR

The wax seal on one or more toilets is failing. This condition may allow moisture intrusion which may cause damage to surrounding components. The inspector recommends further evaluation and repair by a qualified professional.

Recommendation

Contact a qualified plumbing contractor.

 Recommendation



7.5.1 Water Heater

WATER HEATER - EXCESSIVE TEMPERATURE

KITCHEN

At the time of the inspection the temperature of the water in the kitchen was 135 Degrees F. This condition may be a scalding hazard. The inspector recommends further evaluation and repair by a qualified professional.

 Safety Hazard

Recommendation
Contact a qualified plumbing contractor.



8.1.1 Foundation Walls

EFFLORESCENCE

BASEMENT

One or more foundation walls showed signs of efflorescence. Efflorescence is a white, powdery deposit that is consistent with moisture intrusion. This can compromise the soil's ability to support the home structure and/or lead to mold growth. The inspector recommends the affected walls be evaluated by a qualified contractor to identify the source of moisture and repair.

Recommendation
Contact a foundation contractor.



9.4.1 Distribution Systems

BASEBOARD - NO COVER

One or more sections of baseboard heating elements were not covered. This condition is a burn hazard especially to small children. The elements are also susceptible to damage if not covered. The inspector recommends further evaluation and repair of all of the baseboard heating elements by a qualified professional.

Recommendation
Contact a qualified heating and cooling contractor



Laundry Room

10.2.1 Condensate Tube

CONDENSATE - OVERFLOW PAN (NO ALARM)

ATTIC

The air handler does not have an high water alarm on the condensation overflow pan. This condition may allow condensation to overflow the pan without being noticed until damage is done to surrounding components. The inspector recommends further evaluation and repair by a qualified professional.

Recommendation
Contact a qualified heating and cooling contractor



Recommendation



10.3.1 Refrigerant Lines

MISSING SUCTION LINE INSULATION

The suction line insulation is not adequate and is in poor condition. This condition may cause the condensing coil to operate less efficiently. The inspector recommends complete insulation of the refrigerant line by a qualified handyman or contractor.

Recommendation
Contact a handyman or DIY project



Recommendation



12.3.1 Walls & Firewalls

GARAGE WALL - MOISTURE INTRUSION

GARAGE

One or more sections of the garage wall exhibited signs of moisture intrusion. This condition will only worsen over time if not corrected. Which may cause damage to surrounding components. The inspector recommends further evaluation and repair by a qualified professional.

Recommendation
Contact a qualified carpenter.



Recommendation



INTERIOR WALL - PET DAMAGE

 Recommendation

One or more interior walls exhibited signs of pet damage. This is a cosmetic defect to door trim and drywall. The inspector recommends further evaluation and repair by a qualified professional.

Recommendation
Contact a qualified carpenter.



WALL - EFFLORESCENCE

 Recommendation

Recommendation
Contact a foundation contractor.

