



STRILER HOME INSPECTIONS, INC.

508-813-4636

[stilerhomeinspections@gmail.com](mailto:stilerhomeinspections@gmail.com)

<http://www.stilerhi.com>



## YOUR INSPECTION REPORT

1234 Main St.  
Raynham, MA 02767

Buyer Name  
06/03/2019 9:00AM



Inspector  
**Chuck Striler**  
Massachusetts License 726-1HI  
508-813-4636  
[chuck@stilerhi.com](mailto:chuck@stilerhi.com)



Agent  
Agent Name  
555-555-5555  
[agent@spectora.com](mailto:agent@spectora.com)

## Table of Contents

Table of Contents	2
SUMMARY	6
1: INSPECTION DETAILS	7
2: DRIVEWAY / LOT / WALKWAY / TREES & LANDSCAPING / WALLS	8
3: ROOF / SKYLIGHT(S) / DRAINAGE SYSTEM(S)	9
4: CHIMNEY(S) / VENT(S)	10
5: BUILDING EXTERIOR / STAIRS / FOUNDATION / BULKHEAD	11
6: DECKS / PORCHES / BALCONIES	12
7: GARAGE	13
8: BASEMENT / FOUNDATION & STRUCTURE	15
9: PLUMBING	19
10: HEATING	23
11: COOLING	25
12: ELECTRICAL	26
13: ATTIC STRUCTURE & VENTILATION	30
14: BATH & LAUNDRY VENTILATION	31
15: INTERIOR	32
16: BUILT-IN APPLIANCES	35
17: FIREPLACE(S) / WOOD STOVE(S) / PELLET STOVE(S)	36
18: RODENTS	37

*About The Home Inspection:*

A home inspection is a non-invasive, visual examination of the accessible areas of the property, designed to identify areas of concern within specific systems or components defined by the Massachusetts State Standards of Practice, that are both observed and deemed material by the inspector at the exact date and time of inspection. Any and all recommendations for repair, replacement, evaluation, and maintenance issues found, should be evaluated by the appropriate trades contractors within the clients inspection contingency window or prior to closing, which is contract applicable, in order to obtain proper dollar amount estimates on the cost of said repairs and also because these evaluations could uncover more potential issues than able to be noted from a purely visual inspection of the property.

This inspection will not reveal every concern or issue that exists, but only those material defects that were observable on the day of the inspection. This inspection is intended to assist in the evaluation of the overall condition of the dwelling only. This inspection is not a prediction of future conditions and conditions with the property are subject to change the moment we leave the premises.

*Not a Code Inspection:*

The General Home Inspection is not a building code-compliance inspection, but a visual inspection for safety and system defects. The Inspection Report may comment on and identify as problems systems, components and/or conditions which may violate building codes, but although safety defects and building code violations may coincide at the time of the inspection, confirmation of compliance with any building code or identification of any building code violation is not the goal of this Inspection Report and lies beyond the scope of the General Home Inspection.

If you wish to ascertain the degree to which the home complies with any applicable building codes, you should schedule a code-compliance inspection.

*Photos:*

Throughout the inspection report, you may see photos of different systems in need of repair or replacement, as well as other unfavorable conditions. Keep in mind as you look at these photos that they are only examples, other defects may and often do exist. We do not photograph every defect, it would be virtually impossible.

It's important that you remember when an issue is noted that some examples are shown, others may exist, check all areas and repair as needed. Further investigation by yourself or a qualified contractor is needed to locate all issues to be repaired.

*"Limitations" Tab:*

There may be areas in the report where you'll see a tab to the right of the "Information" tab that says "Limitations". It's very important that you take the time to read those limitations. They explain why we were unable to see or report on an item or system. There may also be additional recommendations there that you should act upon BEFORE the close of sale or your objection deadline.

*Older Homes:*

An older home may not meet many generally-accepted current building standards. Older homes are inspected within the context of the time period in which they were built, taking into account the generally-accepted building practices of that time period. The Inspection Report will comment on unsafe conditions, but problems will be described as defects at the Inspector's discretion. Homes are not required to be constantly upgraded to comply with newly-enacted building codes but are only required to comply with building codes or generally-accepted standards which existed at the time of original construction. An exception may exist when a home is remodeled, depending on the scope of work. New work must usually comply with building codes in effect at the time in which the remodel work is performed.

*Report Terms:*

The term "Appears Serviceable" means that an Item appears functional at the time of the inspection and we did not observe conditions that would lead us to believe problems existed with this system or component. Some serviceable items may show wear and tear. Other conditions may be noted in the body of the report. For example, a brand new home with a very expensive kitchen and an older home with a modest kitchen can both be rated as "Appears Serviceable".

The term "Repair as needed" or "Repair is recommended" is an indication that the noted item is in need of repair. Use whatever means necessary to repair the issue, either per the advice and services of a licensed contractor, or yourself.

The term "Near future" means that an item or system is at, or near the end of its useful life. The lifespan of construction materials and systems fluctuates, depending on many things. We cannot be sure when the component or system will fail. You should consider replacement of the item(s), or at a minimum, monitoring of the item(s).

*Insect / Pest / Wildlife Concerns:*

Inspecting for and reporting on the presence of WDI (Wood Destroying Organisms) activity including, but not limited to: Termites, Powder Post Beetles, Carpenter Ants, Carpenter Bees, etc. is beyond the scope of a home inspection as per the [State of Massachusetts Standards of Practice 266CMR](#) and is excluded from this inspection. It is HIGHLY recommended that you have a WDI-Termite inspection prior to the end of your inspection contingency period. Any comments made in this report in regards to such activity was done as a courtesy only, should not be viewed by an all-inclusive activity, and requires further evaluation by a licensed pest control company.

*Safety and Care:*

While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. During the course of the inspection, the inspector does not enter any area or perform any procedure that may damage the property or its components or be dangerous to or adversely affect the health of the inspector or other persons.

*Timely Evaluation By Contractors:*

Recommendations made by the inspector should be acted upon in a timely manner in order to receive the results of any further evaluation by contractors or engineers before the deadline for negotiation with the seller has passed. If you are unable to get the results of any necessary evaluations before the expiration of your Inspection Objection deadline, you should ask your agent to amend the contract to extend the deadline.

*Additional Resources:*

Municipal contacts are a good resource prior to purchasing a home.

The Fire Dept. can be contacted for prior fires in the house or flooding that caused them to pump out the house, or oil tank permits and records of removal.

The Police Dept. will have records of the community including registered sex offenders.

The Conservation Department. will have records for flood zone maps.

The Building Dept. will have records of additions.

The Tax Dept. will have plot plans.

# SUMMARY



ITEMS INSPECTED



MAINTENANCE ITEM



RECOMMENDATION



SAFETY HAZARD

-  5.15.1 Building Exterior / Stairs / Foundation / Bulkhead - Foundation (Exterior): Shrinkage Crack
-  5.15.2 Building Exterior / Stairs / Foundation / Bulkhead - Foundation (Exterior): Cold Pour Seam
-  7.2.1 Garage - Floor: Cracks (Typical)
-  7.2.2 Garage - Floor: Expansion Cracks
-  7.8.1 Garage - Occupant Door (From Garage To Home): Not Self-Closing
-  8.2.1 Basement / Foundation & Structure - Interior Foundation: Poured Concrete (-1/4 Inch Crack)
-  8.2.2 Basement / Foundation & Structure - Interior Foundation: Foundation (Cracks Repaired)
-  8.4.1 Basement / Foundation & Structure - Floor: Common Cracks
-  9.10.1 Plumbing - Sewage Pump: Description
-  10.10.1 Heating - Duct System: Sheet Metal (Humidifier Installed)
-  12.3.1 Electrical - Panel Enclosure & Cover: Panel Enclosure (Missing KO)
-  12.4.1 Electrical - Interior Wiring In Panel: Older Wiring Techniques
-  12.4.2 Electrical - Interior Wiring In Panel: Neutral Bar (Neutral And Ground, Same Screw)
-  12.4.3 Electrical - Interior Wiring In Panel: Breaker (Multi Tap)
-  13.1.1 Attic Structure & Ventilation - Access: Sealed
-  18.1.1 Rodents - Visual Signs: Traps

# 1: INSPECTION DETAILS

## Information

---

**Inspection Details: Inspected By**

Chuck Striler

**Inspection Details: Start Time**

9am

The inspection began at or around the time listed above.

**Inspection Details: Finish Time**

10:30am

The inspection finished at or around the time listed above.

**Inspection Details: Weather Conditions**

Clear

**Inspection Details: People In Attendance**

Buyer(s), Buyer's Agent

**Inspection Details: Type of Building**

Single Family

**Inspection Details: Service(s) Provided**

Home Inspection

**Inspection Details: Space Below Grade**

Basement

**Inspection Details: Temperature (Approximate Range)**

50-60deg

The temperature at the time of inspection was between the noted range above, measured in Fahrenheit.

## 2: DRIVEWAY / LOT / WALKWAY / TREES & LANDSCAPING / WALLS

### Information

---

**Driveway / Parking Lot: Paving Material(s)**

Asphalt



**Driveway / Parking Lot: Condition**

Appear(s) Serviceable

**Walkway(s): Materials**

Pavers



**Walkway(s): Condition**

Appear(s) Serviceable

**Retaining Wall(s): Materials**

None Present

**Lot Drainage: Condition**

Appear(s) Serviceable

**Drainage At Foundation: Condition**

Appear(s) Serviceable

**Tree(s): Condition**

Appear(s) Serviceable

**Landscaping: Condition**

Appear(s) Serviceable

**Grounds Notes**

This inspection is not intended to address or include any geological conditions or site stability information. For information concerning these conditions, a geologist or soils engineer should be consulted.

Any reference to grade is limited to only areas around the exterior of the exposed areas of foundation or exterior walls.

This inspection is visual in nature and does not attempt to determine drainage performance of the site or the condition of any underground piping, including municipal water and sewer service piping or septic systems.



## 3: ROOF / SKYLIGHT(S) / DRAINAGE SYSTEM(S)

### Information

#### Roof Coverings: Inspection

##### Method

Binoculars

#### Roof Coverings: Material(s)

Asphalt

#### Roof Coverings: Condition

Appear(s) Serviceable

#### Roof Flashings: Condition

Appear(s) Serviceable

#### Roof Penetrations: Type

Plumbing Vent Stack

#### Roof Penetrations: Condition

Appear(s) Serviceable

#### Drainage Systems: Type

Full Gutters, Aluminum

#### Drainage Systems: Condition

Appear(s) Serviceable

#### Roof Flashings: Description

Metal

"Flashing" is a general term used to describe multiple products fabricated into shapes used to protect areas of the roof from moisture intrusion. Typical areas of installation include roof and wall penetrations such as vent pipes, chimneys, skylights and areas where dissimilar roofing materials or different roof slopes meet.

#### Notes: Observation Limits

Company Policy

During your inspection, our inspectors will make every effort to safely view the roof of the home from several vantage points. But, as per our company policy, our inspectors **DO NOT** walk on roofing.

There is the great probability that damage to the roofing material or other components on the roof may occur. In addition to that, the potential for injury to our employees is a chance we are not willing to take.

Therefore, the client is advised that this is a limited review and a qualified roofer should be contacted if a more detailed opinion is desired.

#### Notes: Lifespan Factors

Lifespan factors (DISCLAIMER)

Because of the many variables which affect the lifespan of roof-covering materials, the Inspector does not provide an estimate of the expected long-term service life of any roof-covering materials. This is in accordance with all inspection industry Standards of Practice.

The following factors can affect the lifespan of roof-covering materials and its ability to shed water:

Roofing material quality: Better quality materials generally last longer.

Installation method: Improper installation may reduce lifespan.

The number of layers: Roofs installed over existing roofs will have reduced lifespan.

Structure orientation: South-facing roofs will have shorter life spans.

The degree of roof slope: Flatter roofs will have shorter life spans.

Climate zone (snow & rain): Harsh climates shorten roof lifespans.

Temperature swings: climates with large daily temperature differentials (within 24-hour cycles) will shorten roof lifespans.

Homesite conditions (overhanging tree branches, wind, etc.)

Roof color: Darker roofs absorb more heat which shortens roof lifespan.

Elevation: Homes at higher elevations are exposed to more ultraviolet (UV) light, which shortens roof lifespan.

Home orientation: Roofs which receive more sun deteriorate more quickly than roofs which receive less sun.

Roof structure ventilation: Poor ventilation shortens roof lifespans.

Quality of maintenance: Poor maintenance will reduce lifespan.

## 4: CHIMNEY(S) / VENT(S)

### Information

---

**Type: Chimney Or Vent Material**  
Metal, PVC

**Type: Chimney Or Vent Condition**  
Appear(s) Serviceable

**Type: Chimney Or Vent Photo(s)**



# 5: BUILDING EXTERIOR / STAIRS / FOUNDATION / BULKHEAD

## Information

### Exterior Walls Materials: Siding Material(s)

Vinyl

### Exterior Walls Materials: Condition

Appear(s) Serviceable

### Exterior Trim / Trim Flashing: Materials

Vinyl, Metal

### Exterior Trim / Trim Flashing: Condition

Appear(s) Serviceable

### Exterior Window Trim: Materials

Vinyl

### Exterior Window Trim: Condition

Appear(s) Serviceable

### Foundation (Exterior): Materials

Poured Concrete

### Foundation (Exterior): Condition

Appear(s) Serviceable

### Window Wells: Condition

None Present

### Bulkhead: Type

None Present

## Observations

### 5.15.1 Foundation (Exterior)



Maintenance Item

### SHRINKAGE CRACK

One or more walls have hairline cracks. They appear to be shrinkage cracks. Shrinkage cracks are caused by the evaporation of water in the mix. This is a normal condition. As the concrete cures and dries it "shrinks" leaving hairline cracks. Seventy-five percent of all shrinkage cracks appear in the first year. Monitor and repair if needed.



Right


### 5.15.2 Foundation (Exterior)



Recommendation

### COLD POUR SEAM

A cold pour joint was noted. Cold pour joints occur because of the time delay between subsequent "pours" into the foundation forms.



Rear

## 6: DECKS / PORCHES / BALCONIES

### Information

#### Deck(s): Structure Type

Deck



#### Deck(s): Materials

Wood

#### Deck(s): Access

Full

#### Porch(es): Structure Type

Porch



#### Porch(es): Materials

Wood & Composite Decking

#### Deck(s): Condition

Appear(s) Serviceable

Inspection of the structures typically includes the following including the following:  
Attachment to the home (fastening method and flashing)

Structural integrity

Planking (flooring)

Guardrails

Finish coatings

Stairs (including treads, risers, attachment to the structure, supports and handrail).

#### Porch(es): Condition

Appear(s) Serviceable

Inspection of the structures typically includes the following including the following:  
Attachment to the home (fastening method and flashing)

Structural integrity

Planking (flooring)

Guardrails

Finish coatings

Stairs (including treads, risers, attachment to the structure, supports and handrail).

# 7: GARAGE

## Information

**Type: Type**

Attached

**Floor: Access**

Full

**Floor: Condition**

Appear(s) Serviceable



**Ceiling: Access**

Full

**Ceiling: Condition**

Appear(s) Serviceable

**Walls & Firewalls: Access**

Full

**Walls & Firewalls: Condition**

Appear(s) Serviceable

**Support Post(s): Access**

None Present

**Overhead Door(s): Condition**

Appear(s) Serviceable

**Door Opener(s): Condition**

Appear(s) Serviceable

**Occupant Door (From Garage To Home): Condition**

Appear(s) Serviceable

## Observations

7.2.1 Floor

### CRACKS (TYPICAL)

Typical cracks were noted. Seal as needed.

Recommendation


Contact a handyman or DIY project



7.2.2 Floor

### EXPANSION CRACKS

"Expansion Cracks" were noted in the floor. This is an intentional building method designed to limit the anticipated cracking that occurs in concrete floors and is not a structural concern.



7.8.1 Occupant Door (From Garage To Home)



Safety Hazard

### **NOT SELF-CLOSING**

The door from the garage to the home should have self-closing hinges to help prevent the spread of a fire to living space. Recommend installing self-closing hinges.

Recommendation

Contact a qualified handyman.





## 8: BASEMENT / FOUNDATION & STRUCTURE

### Information

**Interior Foundation: Access**

Partial

**Interior Foundation: Material**

Concrete

**Interior Foundation: Condition**

Appear(s) Serviceable

**Exit / Entry Door: Type**

Steel

**Exit / Entry Door: Condition**

Appear(s) Serviceable

**Floor: Access**

Partial

**Floor: Condition**

Appear(s) Serviceable

**Means Of Egress: Condition**

Full Egress, Walk Out Door

**Sills: Access**

Partial

**Sills: Condition**

Appear(s) Serviceable

**Floor Joists: Access**

Partial

**Floor Joists: Condition**

Appear(s) Serviceable

**Subfloor: Access**

Inaccessible

**Beams: Access**

Partial

**Beams: Material**

Prelaminated (LVL)

**Beams: Condition**

Appear(s) Serviceable

**Posts / Columns: Access**

Partial

**Posts / Columns: Type**

Steel

**Posts / Columns: Condition**

Appear(s) Serviceable

**Dehumidifier: Condition**

None Present

**Basement Access: Access**

Partially Finished

Areas hidden from view by finished walls or stored items cannot be judged and are not a part of this inspection.

**Basement Access: Basement Photos**

**Floor: Type**

Concrete

All concrete floor slabs experience some degree of cracking due to shrinkage in the drying process.

In most instances, floor coverings prevent recognition of cracks or settlement in all but the most severe cases. Where carpeting and other floor coverings are installed, the materials and condition of the flooring underneath cannot be determined.

## Means Of Egress: Basement Egress Information

Egress is another word for exit and is used in building code to refer to the means by which somebody can exit a building.

A basement emergency exit normally comes in the form of egress windows. These are large windows that can be opened up to allow people in the basement to easily get out and allow firefighters in. Because many house fires begin in the basement, laws in almost every part of the country require these windows in finished basement bedrooms; and you can face serious fines and penalties if they're not installed to code.

For safety, it is important that a bedroom a place where someone would be sleeping needs to have at least two ways to get out if necessary. The first means of egress is a door, the one that allows entry and exit into the room. The second would be a code compliant window or windows.

Not all basement windows are egress windows. For instance, if you have an unfinished basement, it may have ventilation windows. These probably wouldn't meet the code for egress windows. For a bedroom, one of the means of egress needs to go to the outside of the building.

For more information regarding basement egress and safety, check with your local building inspector.

## Limitations

---

Interior Foundation

### **PARTIAL ACCESS**

Finish Materials, Stored Items

One or more areas of the foundation were partially inaccessible at the time of inspection due to the noted item(s).

---

Floor

### **PARTIALLY INACCESSIBLE**

Storage

Areas that are covered with rugs, vinyl tiles, ceramic tiles, wood, stored items, etc. are inaccessible.

---

Sills

### **PARTIAL ACCESS**

Finish Materials, Insulation

One or more sills was only partially accessible due to the item(s) noted above.


---

Floor Joists

### **PARTIAL ACCESS**

Insulation, Finished Ceiling

One or more floor joists were only partially accessible due to the item(s) noted above.





Subfloor

**PARTIAL ACCESS**

Insulation, Finished Ceiling

One or more areas of the subfloor were only partially accessible due to the item(s) noted above.

**Observations**

8.2.1 Interior Foundation

 Maintenance Item

**POURED CONCRETE (-1/4 INCH CRACK)**

One or more cracks less than 1/4 inch were noted in the foundation walls. Consider sealing and monitoring for future cracking.

Recommendation

Contact a handyman or DIY project



Rear



Right



Front



Front

8.2.2 Interior Foundation

 Recommendation

**FOUNDATION (CRACKS REPAIRED)**

Epoxy repairs have been made, consult owner for warranty.



## 8.4.1 Floor

**COMMON CRACKS**

Common cracks were visible in the basement floor. This type of cracking can have several causes

- concrete shrinkage, which is a normal part of the concrete curing process and not a structural concern
- post-construction settling due to incomplete compaction of the soil beneath the slab during construction. This also is not an unusual condition and typically would not continue.
- heaving of the soil due to the presence of expansive soils.

Determining the cause of cracking lies beyond the scope of the General Home Inspection. Consider repairing cracks as needed and monitor.

## Recommendation

Contact a handyman or DIY project



# 9: PLUMBING

## Information

**Water Source: Water Source**  
Public

**Main Water Supply: Main Water Shutoff Photo**

**Main Water Supply: Piping Material**  
Copper



**Domestic Water Supply System: Material**  
Plastic

**Domestic Water Supply System: Condition**  
Appear(s) Serviceable

**Drain, Waste, & Vent Systems: Main Cleanout Photo**




**Drain, Waste, & Vent Systems: Material**  
PVC

**Drain, Waste, & Vent Systems: Condition**  
Appear(s) Serviceable

**Domestic Hot Water System(s): Hot Water System Photo**



**Domestic Hot Water System(s):  
Manufacturer's Label Photo**



**Domestic Hot Water System(s):  
Water Supply Shutoff Photo  
Below**



**Domestic Hot Water System(s):  
Type  
On Demand**

**Domestic Hot Water System(s):  
Condition  
Appear(s) Serviceable**

**Sump Pump(s): Condition  
None Present**

**Sewage Pump: Condition  
Appear(s) Serviceable**



**Oil / Natural Gas / Propane  
System(s): Fuel Supply Photo(s)**



**Oil / Natural Gas / Propane  
System(s): Condition  
Appear(s) Serviceable**

**Laundry: Laundry Photo**



**Toilet(s): Condition  
Appear(s) Serviceable**

**Main Water Supply: Condition  
Appear(s) Serviceable**

Our comments on the condition of the Main Water Shutoff are based solely on our visual observation, we do NOT test valves for operation.

**Laundry: Appliances Not Tested**

Laundry appliances, if installed, are not tested or moved during the inspection and the condition of any walls or flooring hidden by them cannot be judged. Drain lines and water supply valves serving washing machines are not operated. Water supply valves may be subject to leaking if turned.

### Laundry: Use Stainless Steel Hoses

We recommend using stainless steel type hoses, if not already in use, to prevent potential water damage from a burst hose.



### Sinks / Vanity: Condition

Appear(s) Serviceable

Items that are typically checked include but are not limited to:

- Faucets
- Supply Lines
- Supply Line Shutoffs
- Drain Pipes
- Functional drainage.

### Tubs / Showers: Condition

Appear(s) Serviceable

Items that are typically checked include but are not limited to:

- Mixing Valves
- Shower Heads
- Functional Drainage
- Stopper Function

## Limitations

---

Domestic Water Supply System

### INACCESSIBLE DUE TO FINISH MATERIALS

Some supply lines were not fully accessible due to the wall, floor, and or ceiling coverings.





Drain, Waste, & Vent Systems

## INACCESSIBLE DUE TO FINISH MATERIALS

Some drain, waste, and vent pipes were not fully accessible due to the wall, floor, and or ceiling coverings.



## Observations

---

9.10.1 Sewage Pump



### DESCRIPTION

One or more sewage pumps are installed.

A sewage ejector pump, also called a pump-up ejector system, is used when a bathroom, laundry room or any other type of plumbing fixture is located below the level of the main sewer or septic line flowing from the house. Because the flow of drain-wastewater depends on gravity, plumbing systems in which these fixtures are located below the level of the main sewer line all require some means of elevating the wastewater so it can flow properly.

This unit requires periodic maintenance and should be connected to an alarm to warn of failure.

Recommendation

Contact a qualified professional.

# 10: HEATING

## Information

### Heating System Information:

#### Fuel Source

Natural Gas

### Duct System: Type

Sheet Metal (Insulated), Flexible  
Round (Insulated)

### Heating System Information:

#### Flue Type

PVC

### Duct System: Condition

Appear(s) Serviceable

### Heating System Information:

#### Condition


Appear(s) Serviceable

### Normal Operating Controls:

#### Condition

Appear(s) Serviceable

### Heating System Photo(s)



### Forced Air System

Heat for the home was supplied by one or more forced air system(s).

This type of system has a furnace as a heat source. Cold air is drawn from the house and is fed into the furnace where the air is heated and circulated back into the house via a duct system and into rooms through registers.

*Items that are typically checked for specific systems include, but are not limited to:*

Cabinet - Blower Fan - Flue Fan - Burner - Flue - Blower Fan Safety Switch

**Notes: Service History? Check With Owner**

Heating systems should be serviced annually. Check with the current owner as to when the heating system(s) in this home was serviced last.

If no record of service can be found, or the system hasn't been serviced within the last year, then servicing and a full evaluation is recommended BEFORE the close of sale.

**Notes: Heating Notes**

The inspector is not equipped to inspect furnace heat exchangers for evidence of cracks or holes, as this can only be done by dismantling the unit. This is beyond the scope of this inspection. Some furnaces are designed in such a way that inspection is almost impossible.

The inspector can not light pilot lights.

Safety devices are not tested by the inspector.

Thermostats are not checked for calibration or timed functions.

Adequacy, efficiency or the even distribution of air throughout a building cannot be addressed by visual inspection.

Electronic air cleaners, humidifiers, and dehumidifiers are beyond the scope of this inspection. You should have these systems evaluated by a qualified individual.

The inspector does not perform pressure tests on coolant systems, therefore no representation is made regarding coolant charge or line integrity.

Subjective judgment of system capacity is not a part of the inspection.

Determining the condition of oil tanks, whether exposed or buried, is beyond the scope of this inspection. Leaking oil tanks represent an environmental hazard which is sometimes costly to remedy.

During this inspection, it is impossible to determine the condition of the interior of the flue. The interior of the flue may be deteriorated, but during a visual inspection, we were unable to see the interior walls.

Asbestos materials have been commonly used in heating systems. Determining the presence of asbestos can ONLY be performed by laboratory testing and is beyond the scope of this inspection.

**Observations**

## 10.10.1 Duct System



Maintenance Item

**SHEET METAL (HUMIDIFIER INSTALLED)**

The ductwork has a humidifier installed in the plenum. Humidifiers can increase interior home comfort in the winter if maintained properly. If no maintenance information is available from the homeowner, then we recommend checking online for information about your particular model and it's operation.

Recommendation

Recommended DIY Project





# 11: COOLING

## Information

---

**Cooling System Type: Type(s)**  
Central Air Conditioner

**Cooling System Type: Condenser Photo(s)**

**Cooling System Type: Cooling Photos**



**Cooling System Type: Condition**

Appear(s) Serviceable

Weather permitting, items that are typically checked include but are not limited to:

Cabinet - Blower Fan - 220V Disconnect Switch - Insulation On Suction Line - Condensing Coil General Condition - Condensate Pump (Noted But Not Tested) - Condensate Pan In Attic - Pan Float Switch (Noted But Not Tested)

# 12: ELECTRICAL

## Information

**Service Entry: Service Entry Photo(s)**



**Service Entry: Voltage**  
120/240 volts

**Service Entry: Condition**  
Appear(s) Serviceable

**Panel Type(s), Amperage & Grounding: Type**  
Main Circuit Breaker

**Panel Type(s), Amperage & Grounding: Amperage Of Main Panel**  
200 AMP

**Panel Type(s), Amperage & Grounding: Ground Wire Type / Connected To**  
Copper, Main Water Line


**Panel Enclosure & Cover: Exterior Photo**



**Panel Enclosure & Cover: Main Disconnect Type**  
Main Breaker In Panel

**Panel Enclosure & Cover: Condition**  
Appear(s) Serviceable

**Interior Wiring In Panel: Interior Photo**



**Interior Wiring In Panel: Service Entry Feeder Wire Type**

Aluminum

**Interior Wiring In Panel: Condition**

Appear(s) Serviceable

**Branch Circuit Wiring: Type**

Non Metallic (Romex)

**Branch Circuit Wiring: Condition**

Appear(s) Serviceable

**Switches, Receptacles & Lighting Fixtures: Condition**

Appear(s) Serviceable

**Service Entry: Service Entry Type**

Underground

Components inspected typically include the following:

- Masthead
- Mast condition and support
- Service entrance cable or pipe
- Weatherhead
- Meter condition
- Service Drop Conductors
- Drip loop

## Notes: Information

A wide variety of electrical systems have been installed over the years and electrical systems have been affected by the following:

The Electrical Code requirements which existed at the time the home was built or additional electrical work was performed.

The abilities and inclinations of the system designer and installers

Original construction budget.

Changes made over the years

Home inspectors are generalists, and although familiarity with electrical systems is a fundamental part of the home inspection, inspectors are not electricians, and will not be familiar with all electrical systems and components installed over the years. Electrical standards and codes have evolved over the years and home electrical systems and their components are required to comply only with codes which were in effect at the time the home was built or the additional work was performed.

A Home Inspectors concern with electrical systems is not it's code compliance but the degree to which the installed electrical system safely provides for the electrical requirements of the home. The home inspectors concern will be commenting on safety and system defects, not code violations. Some conditions commented upon may not be code violations and some code violations may not be commented upon.

If in the opinion of the Inspector, the installed electrical system or any of its components is failing or may fail to safely provide for the electrical requirements of the home, the Inspector will recommend evaluation and/or correction by a qualified electrical contractor.

Any electrical recommendations should be considered high priority items since all electrical issues are safety concerns.

Any electrical repairs attempted by anyone other than a licensed electrician is not recommended. Always hire a licensed electrician for even the smallest repair.

Home branch circuit wiring consists of devices such as switches, outlets, connections for permanently-wired appliances and the electrical conductors which supply them with electricity. Most conductors are hidden behind the floor, wall and ceiling coverings and cannot be evaluated by the inspector. The Inspector does not remove cover plates and inspection of branch wiring is limited to the proper response to testing of switches and electrical outlets.

Aluminum wiring requires periodic inspection and maintenance by a licensed electrician.

Operation of time clock motors is not verified.

Inoperative light fixtures often lack bulbs or have dead bulbs installed. Light bulbs are not changed during the inspection, due to time constraints.

We recommend regular testing as per Fire Department guidelines.

## Observations

### 12.3.1 Panel Enclosure & Cover

#### PANEL ENCLOSURE (MISSING KO)




Recommendation

Unfilled holes or knockouts in the main electrical service panel were noted. A knockout seal is recommended.

Recommendation

Contact a qualified electrical contractor.



### 12.4.1 Interior Wiring In Panel

#### OLDER WIRING TECHNIQUES



Recommendation

Older wiring techniques were noted. Consider having a qualified contractor update to current standards.

Recommendation

Contact a qualified electrical contractor.




12.4.2 Interior Wiring In Panel

**NEUTRAL BAR (NEUTRAL AND GROUND, SAME SCREW)**

Older wiring technique. One or more neutral (white) wires and ground (bare copper) wires were attached under the same screw in the panel. This is not up to current standards. Consider updating.

Recommendation

Contact a qualified electrical contractor.




12.4.3 Interior Wiring In Panel

**BREAKER (MULTI TAP)**

Two or more wires were connected to a breaker designed for only one wire. This is known as a "multi-tap" and is a defective condition. Further evaluation and or repair is recommended.

Recommendation

Contact a qualified electrical contractor.





# 13: ATTIC STRUCTURE & VENTILATION

## Information

**Access: Access Type**

Pull Down Ladder

**Access: Access Condition**

Inaccessible

**Access: Access Note**

In accordance with our standards, we do not attempt to enter attics that are not readily accessible, or walk on the exposed and/or insulation covered framing members, in which case we would inspect them as best we can from the access point.

## Observations

## 13.1.1 Access

**SEALED**

The cover to the attic hatch was physically sealed and we were unable to remove it without causing damage. No comment on any items related to the attic or ventilation is possible.



Recommendation



# 14: BATH & LAUNDRY VENTILATION

## Information

### Bath Vent: Condition

Appear(s) Serviceable

### Laundry Vent : Condition

Appear(s) Serviceable


### Laundry Vent : Dryer Vent Safety

#### Overheated Clothes Dryers Can Cause Fires

Fires can occur when lint builds up in the dryer or in the exhaust duct. Lint can block the flow of air, cause excessive heat build-up, and result in a fire in some dryers.

#### To help prevent fires:

- **Clean the lint screen/filter before or after drying each load of clothes.** If clothing is still damp at the end of a typical drying cycle or drying requires longer times than normal, this may be a sign that the lint screen or the exhaust duct is blocked.
- **Clean the dryer vent and exhaust duct periodically.** Check the outside dryer vent while the dryer is operating to make sure exhaust air is escaping. If it is not, the vent or the exhaust duct may be blocked. To remove a blockage in the exhaust path, it may be necessary to disconnect the exhaust duct from the dryer. Remember to reconnect the ducting to the dryer and outside vent before using the dryer again.
- **Clean behind the dryer, where lint can build up.** Have a qualified service person clean the interior of the dryer chassis periodically to minimize the amount of lint accumulation. Keep the area around the dryer clean and free of clutter.
- **Replace plastic or foil, accordion-type ducting material with rigid or corrugated semi-rigid metal duct.** Most manufacturers specify the use of a rigid or corrugated semi-rigid metal duct, which provides maximum airflow. The flexible plastic or foil type duct can more easily trap lint and is more susceptible to kinks or crushing, which can greatly reduce the airflow.
- **Take special care when drying clothes that have been soiled with volatile chemicals** such as gasoline, cooking oils, cleaning agents, or finishing oils and stains. If possible, wash the clothing more than once to minimize the number of volatile chemicals on the clothes and, preferably, hang the clothes to dry. If using a dryer, use the lowest heat setting and a drying cycle that has a cool-down period at the end of the cycle. To prevent clothes from igniting after drying, do not leave the dried clothes in the dryer or piled in a laundry basket.



# 15: INTERIOR

## Information

---

**Interior Doors: Condition**

Appear(s) Serviceable

**Ceilings: Condition**

Appear(s) Serviceable

**Exterior Doors: Condition**

Appear(s) Serviceable

**Windows: Condition**

Appear(s) Serviceable

**Floors: Condition**

Appear(s) Serviceable

**Kitchen / Bath Cabinets:  
Condition**

Appear(s) Serviceable

**Walls: Condition**

Appear(s) Serviceable

**Heat Source: Condition**

All Rooms Had A Heat Source



**Room Photos**

The photos below identify some or all of the rooms in the building.



**Notes: Interior Notes**

Our inspection of living space includes the visually accessible areas of walls, floors, cabinets and closets, and the testing of a representative number of windows and doors, switches and outlets. We do not evaluate window treatments, move furnishings or possessions, lift carpets or rugs, empty closets or cabinets, nor comment on cosmetic deficiencies.

We may not comment on cracks that appear around windows and doors, along lines of framing members or along seams of drywall and plasterboard. These are typically caused by minor movements, such as wood shrinkage, common settling, and seismic activity, and will often reappear if they are not correctly repaired. Such cracks can become the subject of disputes, and are therefore best evaluated by a specialist.

Floor covering damage or stains may be hidden by furniture, and the condition of floors underlying floor coverings is not inspected.

Determining the condition of insulated glass windows is not always possible due to temperature, cleanliness of the glass, weather and lighting conditions. Check with owners for further information.

Testing, identifying, or identifying the source of environmental pollutants or odors (including but not limited to lead, mold, allergens, odors from household pets and cigarette smoke) is beyond the scope of our service, but can become equally contentious or difficult to eradicate. We recommend you carefully determine and schedule whatever remedial services may be deemed advisable or necessary before the close of escrow.

# 16: BUILT-IN APPLIANCES

## Information

---

**Range / Oven / Cooktop: Range / Range / Oven / Cooktop:**

**Oven Fuel Source**

Gas

**Condition**

Appear(s) Serviceable

**Range Hood: Condition**

None Present

**Dishwasher: Condition**

Appear(s) Serviceable

**Garbage Disposal: Condition**

None Present

**Built-in Microwave: Condition**

Appear(s) Serviceable

**Notes: Appliance Note**

As per our Standards of Practice, our inspection of appliances is limited to permanently installed cooking appliances, dishwashers, and garbage disposals.

# 17: FIREPLACE(S) / WOOD STOVE(S) / PELLET STOVE(S)

## Information

---

**Type: Type**

Natural Gas Fireplace

**Type: Condition**

Appear(s) Serviceable



# 18: RODENTS

## Information

---

### Visual Signs: Rodent Signs

Traps

One or more signs of current or past rodent activity were noted.

## Observations

---

18.1.1 Visual Signs

 Recommendation

### TRAPS

One or more "mouse traps" were noted.

Check with the current owner regarding the history of rodents and treatment.

Recommendation

Contact a qualified pest control specialist.

