



7.2.2 Main & Subpanels, Service & Grounding, Main Overcurrent Device



PANEL DOESNT CLOSE PROPERLY

Electrical panel door does not close properly. Additionally the exterior electrical panel is exposed to potential moisture intrusion. Recommend having door repaired to prevent water from infiltrating panel and electrical wiring.

Recommendation
Contact a qualified electrical contractor.



7.4.1 Lighting Fixtures, Switches & Receptacles

COVER PLATES MISSING



One or more receptacles are missing a cover plate. This causes short and shock risk. Recommend installation of plates.

Recommendation

Contact a qualified electrical contractor.



Southwest Bedroom

7.7.1 Carbon Monoxide Detectors

MISSING CO DETECTOR

No Carbon Monoxide detector found on main level. A carbon-monoxide detector should be installed on every level, in the same room as a fireplace, and within 15 feet of bedrooms.



9.1.2 Doors

HARDWARE MISSING



BACK DOOR BY LAUNDRY

Having all hardware is recommended to prevent potential safety hazard or forced entry.

Recommendation Contact a qualified handyman.



9.8.1 Plumbing fixtures

IMPROPER PLUMBING



Sink faucet was installed incorrectly. Recommend turning faucet 90 degrees to the right. Additionally, this will help prevent occupants from accidental scalding by turning the faucet in the wrong direction.

Recommendation

Contact a qualified plumbing contractor.

