SUMMARY 1234 Main St. Harleysville PA 19438 Buyer Name 07/29/2019 9:00AM

JONATHAN MUSSELMAN ASHI Certified Inspector MUSSELMAN HOME INSPECTION LLC 267-664-2056

musselmanhomeinspection@gmail.com

3.1.1 Siding, Flashing & Trim CAULKING AND PAINTING

Recommendation

It's important that all exterior components are properly maintained and sealed. Wood and metal products should be painted to prevent material decomposition. Caulking around dissimilar materials and exterior penetrations will help prevent water infiltration to the structure. Monitoring these areas during your bi-annual inspection of the property is very important to keeping a healthy and safe home.

Recommendation Recommended DIY Project




3.5.1 Vegetation, Grading, Drainage & Retaining Walls **NEGATIVE GRADING**



Grading is sloping towards the home in some areas. This could lead to water intrusion and foundation issues. Recommend qualified landscaper or foundation contractor regrade so water flows away from home.

Here is a helpful article discussing negative grading.



3.6.1 Walkways, Patios & Driveways WALKWAY - TRIP HAZARD

Safety Hazard

There is a section of the walkway that is raised or loose causing a trip hazard. Consult a qualified contractor to repair or replace.

Recommendation

Contact a qualified masonry professional.



3.6.2 Walkways, Patios & Driveways UNSEALED GAP AT BUILDING.

Recommendation

The connection between the walkway/hard surface and the building should be sealed with a compatible sealant to keep water out.

Recommendation Contact a qualified professional.



4.1.1 Cooling Equipment AIR FLOW RESTRICTED AROUND UNIT



Air flow to the air conditioner condenser was restricted. This may result in inefficient operation. Recommend cleaning dirt/debris from the unit and cutting vegetation away so that you can freely walk around the unit.

4.1.2 Cooling Equipment **UNIT NOT LEVEL**

The A/C condensing unit is not level. This can cause accelerated deterioration of components. Recommend qualified HVAC contractor level the unit.

AC Condenser - Not Level • Level soil - level unit Normal AC condenser, compressor and coil @ Tom Feiza Mr. Fix-It. I • Settled soil - problem with movement • Tight, bent refrigerant lines, vibration, possible lubrication problems If an AC condenser settles with the soil, the refrigerant lines can be damaged and the compressor may be damaged if operated. A037C

6.2.1 Drain, Waste, & Vent Systems LEAK

There is a plumbing leak. Consult a gualified plumber to evaluate the cause of the leak and correct.

Recommendation Contact a qualified professional.

CSST GAS PIPE BONDING NOT

8.2.1 Grounding system

VERIFIED











Corrugated Stainless Steel Tubing (CSST) must be bonded to the grounding system prior to the use of the product in the house. We were unable to verify that it was bonded to the grounding system. Recommend a gualified plumber evaluate and correct.

Recommendation Contact a qualified professional.




8.3.1 Main and Distribution Panels DOUBLE TAP BREAKER/BREAKERS



BASEMENT

There are breakers with more than one wire connected to them which is called "double tapping". Most electrical breakers are designed for only one wire connection. Consult a qualified electrician to evaluate the electric panel, correct the problems and ensure the panel is safe.

Recommendation Contact a qualified professional.



E0470

9.3.1 Walls MOLD-LIKE SUBSTANCE



BASEMENT

There are signs of a mold-like substance on the wall/s. It is unknown if this is a safety hazard without testing it first to understand what it is. Recommend a qualified mold inspector evaluate and understand proper clean-up procedures.



9.9.1 Windows FAILED THERMAL SEAL



FOYER

Observed condensation between the window panes, which indicates a failed thermal seal. Recommend qualified window contractor to evaluate and repair or replace.




Front Foyer

10.5.1 Exhaust Systems BATHROOM VENTS INTO ATTIC



Bathroom fan vents into the attic, which can cause moisture and mold. Recommend a qualified attic contractor property install exhaust fan to terminate to the exterior.



12.2.1 Gas Fireplace



The gas fireplace was inoperable at inspection. Consult a qualified gas fireplace professional to evaluate and ensure safe operation.

Recommendation Contact a qualified professional.