



inspection_reports@inspectiongeeks.com

3.3.1 Walkways, Patios & Driveways

POSSIBLE TERMITE TREATMENT

FRONT PORCH Recommendation Contact a qualified professional.



3.4.1 Decks, Balconies, Porches & Steps

SHED SIDING ROTTEN AND PEELING PAINT

SHED UNDER DECK Recommendation

Contact a qualified professional.







3.5.1 Eaves, Soffits & Fascia

FASCIA - ROTTED

SOUTHEAST AND NORTHWEST SIDE OF HOUSE

One or more sections of the fascia are rotted. Recommend qualified roofer evaluate & repair.

Recommendation







Inspection Geeks Inc. Page 1 of 9

4.1.1 Foundation

FOUNDATION CRACKS - MINOR

EAST SIDE OF HOUSE

Minor cracking was noted at the foundation. This is common as concrete ages and shrinkage surface cracks are normal. Recommend monitoring for more serious shifting/displacement.

Here is an informational article on foundation cracks.

Recommendation

Contact a qualified structural engineer.





7.2.1 Main & Subpanels, Service & Grounding, Main Overcurrent Device



MAIN PANEL COVER MISSING SCREW

BASEMENT Recommendation Recommended DIY Project



7.2.2 Main & Subpanels, Service & Grounding, Main Overcurrent Device

DOUBLE TAPPED NEUTRAL WIRES

Recommendation

Contact a qualified electrical contractor.



7.3.1 Branch Wiring Circuits, Breakers & Fuses

IMPROPER WIRING

BASEMENT UTILITY ROOM AND BASEMENT BAR

Improper wiring needs attention.

Inspection Geeks Inc. Page 2 of 9

Recommendation

Contact a qualified electrical contractor.





Basement

7.3.2 Branch Wiring Circuits, Breakers & Fuses

IMPROPER ELECTRICAL RECEPTACLE INSTALLATION

ON SHED UNDER DECK Recommendation Contact a qualified professional.





7.3.3 Branch Wiring Circuits, Breakers & Fuses

IMPROPER ELECTRICAL WIRING

BASEMENT UTILITY ROOM Recommendation

Contact a qualified electrical contractor.





Inspection Geeks Inc. Page 3 of 9

7.3.4 Branch Wiring Circuits, Breakers & Fuses

SPLIT ELECTRICAL WIRE

WEST CORNER OF GARAGE UNDER LIGHT FIXTURE Recommendation

Contact a qualified professional.



7.4.1 Lighting Fixtures, Switches & Receptacles

COVER PLATES MISSING

UTILITY ROOM IN BASEMENT

One or more receptacles are missing a cover plate. This causes short and shock risk. Recommend installation of plates.

Recommendation

Contact a qualified electrical contractor.



7.5.1 GFCI & AFCI

NO GFCI PROTECTION INSTALLED

No GFCI protection present in all locations. Recommend licensed electrician upgrade by installing ground fault receptacles in all locations.

Safety Hazard


Here is a link to read about how GFCI receptacles keep you safe.

Recommendation

Contact a qualified electrical contractor.



Kitchen



North Side of House on Patio




Wet bar

Inspection Geeks Inc. Page 4 of 9



North Side of House on Deck





Bathroom (hallway)

Basement Bathroom

8.3.1 Water Supply, Distribution Systems & Fixtures

JETTED TUB PUMP LEAKING

Water dripping observed while jetted tub operating. Recommend inspection and repair by a plumbing professional.

Recommendation

Contact a qualified professional.



Tub Motor Access in Stairway



Tub Motor Access in Stairway

8.4.1 Hot Water Systems, Controls, Flues & Vents


CORREGATED STAINLESS STEEL SUPPLY LINE

Recommend replacement with iron; susceptible to lightening strike.

Recommendation

Contact a qualified plumbing contractor.

Inspection Geeks Inc. Page 5 of 9



Basement

9.4.1 Exhaust Systems

BATHROOM VENT MISSING

Master Bathroom needs bathroom vent.

Recommendation





Hallway Bathroom

Master Bathroom

10.1.1 Doors

DOOR LATCH ALIGNMENT

NORTH BASEMENT ENTRY

Door latch and/or strike plate is out of alignment. Recommend a handyman repair.

Recommendation

Contact a qualified door repair/installation contractor.

Inspection Geeks Inc. Page 6 of 9



Basement Exterior Door

10.2.1 Windows

FAILED SEAL

NORTH WALL IN MASTER BEDROOM

Seal separated from window frame; not allowing casement window to properly close. Recommend securing to allow window to completely close.

Recommendation

Contact a qualified window repair/installation contractor.



10.2.2 Windows

MINOR CRANK DAMAGE

SOUTHWEST MAIN FLOOR BEDROOM

Minor cosmetic damage to crank. Window still opens properly.

Recommendation Recommended DIY Project

Inspection Geeks Inc. Page 7 of 9



10.3.1 Floors

CARPET STAINS

STAIRS TO THE BASEMENT

Carpet had areas of staining or discoloration. Recommend a thorough steam clean by a qualified carpet cleaning company

Recommendation

Contact a qualified cleaning service.



Basement

10.5.1 Ceilings


STAIN(S) ON CEILING

MASTER BEDROOM CLOSET

There is a stain on ceiling/wall that requires repair and paint. Source of staining should be determined.

Recommendation

Contact a qualified professional.



Bedroom closet

Inspection Geeks Inc. Page 8 of 9

12.2.1 Floor

CRACKING

Cracking visible in the garage floor. I recommend a structural engineer evaluate.



Garage

Page 9 of 9 Inspection Geeks Inc.