



2.4.1 Skylights, Chimneys & Other Roof Penetrations CHIMNEY SIDING REPAIR

Siding around chimney was seen to be worn and deteriorating. Recommend siding contractor evaluate and repair.

Recommendation Contact a qualified chimney contractor.



3.1.1 Siding, Flashing & Trim

SIDING ROT/WEAR

East gable vent was found with rotting wood trim.. Recommend a qualified siding contractor evaluate and repair.

Recommendation Contact a qualified professional.



East

3.2.1 Exterior Doors **DOOR SILL/TRIM**

Door sill and/or trim is loose, deteriorated or worn and repair or replacement should be considered.

Recommendation

Contact a qualified door repair/installation contractor.



North

North

3.2.2 Exterior Doors HAZARD

I recommend adjusting the front storm door. It closes quickly and could be a safety hazard.

Recommendation Contact a qualified professional.



3.7.1 Fence DAMAGE

The fence was Leaning and uneven at several sections. I recommend repairing to keep fence structure from further failing.

Recommendation Contact a qualified fencing contractor



5.3.1 Distribution Systems **DUCTS NOT SEALED**

Air supply duct was not properly sealed in attic. Recommend a qualified HVAC contractor evaluate and repair.

Recommendation Contact a qualified HVAC professional.



7.6.1 Jetted Tub

CLEANING

Upon inspection fo the jets, it is recommended for them to be cleaned before full operation. I have linked a helpful article to better assist in proper cleaning of the jets.

https://www.bobvila.com/articles/how-to-clean-a-jetted-tub/

Recommendation Contact a qualified professional.

7.6.2 Jetted Tub

The master tub panel was seen to be pushing back. Recommend front panel be secure to avoid prematurely opening or causing damage.

Recommendation Contact a qualified professional.



8.4.1 Lighting Fixtures, Switches & ReceptaclesLIGHT INOPERABLEOne or more lights are not operating. New light bulb possibly needed.

Recommendation Contact a qualified electrical contractor.







Kitchen

Master Bathroom

Master Bathroom



9.2.1 Ventilation

DRYER VENT

The dryer vent was found with heavy lint buildup. I recommend ensuring the vent is clean to avoid dryer defects and potential fire/safety hazards.

Recommendation Contact a qualified professional.



9.3.1 Exhaust Systems BATHROOM VENTS INTO ATTIC

Bathroom fan vents into the attic, which can cause moisture and mold. Recommend a qualified attic contractor property install exhaust fan to terminate to the exterior or to a larger opening space into attic.

Recommendation Contact a qualified HVAC professional.



10.2.1 Windows WINDOWS STICKING

The windows were operational but hard to open and close. They may need to be lubricated or adjusted for smoother operation. Recommend professional evaluate and advise.

Recommendation Contact a qualified general contractor.

11.3.1 Range/Oven/Cooktop BURNER NOT LIGHTING

Oven light was inoperable during inspection. A new bulb may be needed.



11.4.1 Garbage Disposal **INOPERABLE**

Garbage disposal was inoperable at the time of inspection. It may be stuck in position or have a faulty motor. Recommend qualified handyman repair.

Here is a DIY resource for troubleshooting.

Recommendation Contact a qualified handyman.