

1234 Main St. Northbrook IL 60062

Buyer Name 04/09/2018 9:00AM



2.1.1 Main Roof Coverings

DAMAGED COVERINGS

Roof coverings exhibited general damage that could affect performance. Recommend a qualified roofer evaluate and repair.

Recommendation







2.1.2 Main Roof Coverings

DISCOLORATION

INFORMATION - Roof shingles were discolored, which can be caused by moisture, rust or soot. Recommend a qualified roofing contractor evaluate and remedy with a roof cleaning or repair.

Here is a helpful article about algae stains on roofs.

Recommendation










2.3.1 Skylights, Chimneys & Roof Penetrations

CHIMNEY CROWN CRACKED

The chimney crown had one or more cracks, which can lead to further damage to the chimney structure. Recommend a qualified contractor repair.



2.4.1 Flashings

WORN

Flashings showed signs of wear and tear. This is normal for a roof of this age. Recommend monitoring.

Recommendation

Contact a qualified roofing professional.



The valley flashing is cracked and



Patching around the vent needs to be checked annually.



Patching on the attic fan needs to be inspected once a year.

3.1.1 Siding, Flashing & Trim

IMPROPER CONSTRUCTION PRACTICES

Siding appears to be installed improperly and not up to standards. This could lead to moisture damage or deterioration of the home structure. These openings need to be sealed.

Recommendation

Contact a qualified professional.







3.3.1 Decks, Balconies, Porches & Steps

RAILINGS ARE DAMAGED

Broken railings are present and should be repaired.

Recommendation Contact a handyman or DIY project



3.6.1 Walkways, Patios & Driveways

PATIO CRACKING - MINOR

Normal settling & cracking observed. Recommend monitor and/or patch/seal.

Here is a helpful article on repairing cracked patios.



The patio settled on the left side.

4.1.1 Foundation, Basement & Crawlspaces

FOUNDATION CRACKS - MINOR

Minor cracking was noted at the foundation. This is common as concrete ages and shrinkage surface cracks are normal. Recommend monitoring for more serious shifting/displacement.

Here is an informational article on foundation cracks.

Recommendation

Contact a qualified professional.

5.1.1 Service Entrance Conductors



NOT ENOUGH CLEARANCE

Service drop overhead wires are too low, not giving enough clearance above roof. Recommend contacting your local electric utility company or qualified electrician to see if they can correct.

Recommendation

Contact a qualified electrical contractor.



5.3.1 Branch Circuit Conductors, Overcurrent Devices and Compatibility of Their Amperage & Voltage



EXPOSED ENDS & SPLICES

All wire connections & charged wires with exposed ends and splices should be covered in junction boxes for safety. Recommend a qualified electrician correct.

Recommendation

Contact a qualified electrical contractor.



5.3.2 Branch Circuit Conductors, Overcurrent Devices and Compatibility of Their Amperage & Voltage

IMPROPER WIRING

Improper wiring was observed at the time of inspection. Recommend a licensed electrician evaluate and repair.

Recommendation

Contact a qualified electrical contractor.



NMC is not designed to be installed like this. This type of wiring is not accepted by the local authority.

5.4.1 Outlets, Switches, Lights, and Ceiling Fans

NO GFCI PROTECTION INSTALLED

THE OUTDOOR AND BASEMENT OUTLETS

No GFCI protection present in all locations. Recommend licensed electrician upgrade by installing ground fault receptacles in all locations.

Here is a link to read about how GFCI receptacles keep you safe.

Recommendation

Contact a qualified electrical contractor.



5.4.2 Outlets, Switches, Lights, and Ceiling Fans

OPEN JUNCTION BOX

Open junction box observed. Recommend concealing or replacing.

Recommendation

Recommended DIY Project



5.4.3 Outlets, Switches, Lights, and Ceiling Fans

SWITCHES INSTALLED IMPROPERLY

One or more switches are installed improperly. Recommend licensed electrician repair or replace.

Safety Hazard

Recommendation

Contact a qualified electrical contractor.



There is no 3-way switch to the basement




The outdoor dimmer switch is missing a knob

Safety Hazard

6.4.1 Fuel Storage & Distribution Systems

LEAKING GAS LINE



Recommendation

Contact a qualified plumbing contractor.



8.2.1 Supply Lines

WATER LEAK

An active water leak is present.

8.2.2 Supply Lines

BLACK IRON PIPES ARE USED AS POTABLE DELIVERY



Black iron pipes are not designed for potable water. This should be changed to appropriate material.

8.3.1 Drain, Waste, & Vent Systems

IMPROPER CONNECTIONS OR IMPROPER REPAIR

The waste lines have poor connections or the repair present is not trustworthy.



Duct tape is used on the connection where the pipe leaves the building.

8.4.1 Water Heater

AGE

Water heaters in our area have an average life span of 15 years. It is impossible to say exctly how long your water heater will last. Anytime a water heater is at or past the 15 year mark, you should prepare to replace the unit.

Recommendation

Contact a qualified plumbing contractor.

8.4.2 Water Heater

ANNUAL MAINTENANCE FLUSH NEEDED

Water heaters should be flushed annually to prevent sediment buildup and maintain efficiency. Recommend a qualified plumber service and flush.

Here is a DIY link to help.

Recommendation

Contact a qualified plumbing contractor.

8.4.3 Water Heater

THE WATER HEATER VENTS INTO THE CHIMNEY

The water heater terminates into the chimney. This appliance needs to have a flue liner that carries the exhaust gasses all the way through, up, and out of the chimney. Lack of this liner causes deterioration of the chimney.





9.1.1 Walls

MINOR CRACKS

Minor cracks, nail pops, and other damage were noted on the walls. This is not unusual in a home of this age and these cracks are not a structural concern.

Recommendation

Contact a qualified structural engineer.



9.2.1 Ceilings

MINOR DAMAGE

Minor damage or deterioration to the ceiling was visible at the time of the inspection.

Recommendation

Contact a qualified professional.



Safety Hazard

9.4.1 Doors

DOOR DOESN'T LATCH

Door doesn't latch properly. Recommend handyman repair latch and/or strike plate.

Recommendation


Contact a qualified handyman.



Bedroom door does not lock



Family room door does not lock



The screen is off the track

9.5.1 Windows

DIFFICULT TO OPERATE

Some of the windows were difficult to open, close, or tilt inwards for cleaning. The windows were also drafty and seperated when the locks were engaged.

Recommendation

Contact a handyman or DIY project







10.1.1 Attic Insulation


INSUFFICIENT INSULATION

Insulation depth was inadequate. Recommend a qualified attic insulation contractor install additional insulation.

Recommendation

Contact a qualified insulation contractor.





10.2.1 Wall Insulation

INSUFFICIENT INSULATION

Insulation depth was inadequate. Recommend a qualified attic insulation contractor install additional insulation.

Recommendation
Contact a qualified insulation contractor.






10.3.1 Under Floor and Rim Joist Insulation

INSUFFICIENT INSULATION

Insulation depth was inadequate. Recommend a qualified attic insulation contractor install additional insulation.

Recommendation

Contact a qualified insulation contractor.



11.1.1 Fireplaces, Stoves & Inserts

FIREWALL CRACKED



The brick lining of the fireplace was cracked in one or more places, which could lead to chimney damage or toxic fumes entering the home. Recommend a qualified fireplace contractor evaluate and repair.

A level 2 chimney inspection needs to be performed on both fireplaces and chimneys.

Recommendation

Contact a qualified fireplace contractor.



The fireplace in the family room has cracks in the firebox. This is unsafe to use until a level 2 inspection is performed by a chimney sweep.



This is the fireplace in the piano room. There is a hole in the floor of the firebox. The isolation valve is inside the firebox.

11.3.1 Chimney & Vent Systems

CHIMNEY LINER DIRTY

Chimney liner had layer of creosote dust, so underlying structure couldn't be inspected for cracks. Recommend qualified chimney sweep company inspect and/or clean.

Recommendation

Contact a qualified chimney contractor.




12.5.1 Humidifier

MOLD



The humidifier has mold growing in it. I consider this unhealthy and it should be cleaned.

Recommendation Contact a qualified HVAC professional.



12.5.2 Humidifier

NOT WORKING

The humidifier is not working.

Recommendation
Contact a qualified heating and cooling contractor