

## SUMMARY 1234 Main St.College Station TX 77845 Buyer Name



2.2.1 B. Grading and Drainage

### **EROSION AT DOWNSPOUTS**



Deficiency

Splash blocks or extensions should be installed to the gutter system downspouts where needed to prevent erosion adjacent to the foundation.

12/16/2018 9:00AM

Recommendation

Contact a qualified lawn care professional.



2.4.1 D. Roof Structure & Attic

### MISSING ATTIC INSULATION



Gaps in the insulation can cause condensation and heat loss. Add / replace insulation as necessary for adequate thermal protection

Recommendation

Contact a qualified insulation contractor.



2.4.2 D. Roof Structure & Attic

#### **UTILTITY OBSTRUCTIONS**



Gas and AC drain pipes, and electrical wires crossing the attic walkway floor need to be covered for protection or relocated.



2.5.1 E. Walls (Interior and Exterior)

#### **BROKEN / CRACKED SIDING**

**VARIOUS LOCATIONS** 



All damaged / cracked siding should be repaired or replaced and any cracks sealed to keep the integrity of the weather envelope provided by exterior wall coverings.

Recommendation

Contact a qualified siding specialist.









2.5.2 E. Walls (Interior and Exterior)

### PAINT COVERING NEEDS IMPROVEMENT

Exterior paint is incomplete in several areas.

Recommendation

Contact a qualified painter.












2.5.3 E. Walls (Interior and Exterior)

## **GAPS AT EXTERIOR WALL**

Seal all gaps at joints and utility penetrations to prevent moisture and pest intrusion.



Recommendation Contact a qualified professional.



2.5.4 E. Walls (Interior and Exterior)

## **VOIDS IN MASONRY MORTAR JOINTS**

VARIOUS LOCATIONS


Mortar is less durable than brick, and can be maintained by "repointing." To repoint, chip the old mortar out to a depth of -inch to -inch. Then dampen the joints with water, and repack with new mortar.

Recommendation

Contact a qualified masonry professional.









## 2.5.5 E. Walls (Interior and Exterior)

## INTERIOR UNFINISHED WORK /COSMETIC REPAIRS



Unfinished work, painting and cosmetic repairs or touch ups are needed.

Recommendation Contact a qualified professional.









2.5.6 E. Walls (Interior and Exterior)

### WARPED CLOSET DOWEL RODS

FRONT ENTRY CLOSET, 2ND FLOOR CLOSET Recommendation

Contact a qualified professional.







2.6.1 F. Ceilings and Floors

### COSMETIC REPAIR NEEDED AT FLOOR COVERING.

LIVING ROOM

Flooring has been over cut at floor receptacle.

Recommendation

Contact a qualified professional.







### 2.7.1 G. Doors (Interior and Exterior)

### CABINET HINGES NOT PROPERLY INSTALLED.

A few cabinet doors need hinge adjustment to properly function.

Recommendation Recommended DIY Project





2.7.2 G. Doors (Interior and Exterior)

### DOOR DOESN'T LATCH

LAUNDRY ROOM IRONING BOARD CLOSET

Latch is missing.

Recommendation

Contact a qualified handyman.





2.7.3 G. Doors (Interior and Exterior)

### WEATHERSTRIPPING MISSING

ATTIC ENTRY, FRONT ENTRY

No weatherstripping is installed at the door frame.

Recommendation Recommended DIY Project







2.7.4 G. Doors (Interior and Exterior)

# SELF CLOSING HINGES NEED ADJUSTMENT



Self closing hinges do not provide enough tension to fully close the door.

Recommendation Contact a qualified professional.



2.7.5 G. Doors (Interior and Exterior)

### DOOR HANDLE TRIM INSTALLED OUT OF SQUARE.

FRONT ENTRY, ATTIC ACCESS DOOR Recommendation
Contact a qualified professional.







2.8.1 H. Windows

## LATCH NOT PROPERLY INSTALLED



Window latches needed to prevent unwanted entry and proper function.

Recommendation Contact a qualified professional.



3.2.1 B. Branch Circuits, Connected Devices, and Fixtures

## Deficiency

Maintenance Item

### **EXPOSED ENDS & SPLICES**

ATTIC SPACE

All wire connections & charged wires with exposed ends and splices should be covered in junction boxes for safety. Recommend a qualified electrician correct.

Recommendation

Contact a qualified electrical contractor.



Attic Inder AC Cabinet Plenum

3.2.2 B. Branch Circuits, Connected Devices, and Fixtures




### **CEILING FAN OUT OF BALANCE**

Ceiling fan wobbles when operating. Check for loose fan blades and install balancing kit if necessary.

Recommendation

Contact a qualified professional.



3.2.3 B. Branch Circuits, Connected Devices, and Fixtures



### **UNGROUNDED RECEPTACLE**

LEFT OF FIREPLACE

Check for proper wiring of the electrical receptacle.

Recommendation

Contact a qualified electrical contractor.



4.3.1 C. Duct System, Chases, and Vents

### **EXCESSIVE BENDS IN FLEXIBLE DUCTS**

**VARIOUS LOCATIONS** 

















### 4.3.2 C. Duct System, Chases, and Vents


### NO AIR FLOW IN ZONED BEDROOM




First floor front bedroom did not show any temperature differential when heating system was active. Zone control should be evaluated further by installer.

Recommendation

Contact a qualified professional.







5.1.1 A. Plumbing Supply, Distribution Systems, and Fixtures

### **TUB - SEAL WALL PENETRATIONS**

MASTER BATH

Tub/shower plumbing penetrations need to be sealed.

Recommendation

Contact a handyman or DIY project









5.1.2 A. Plumbing Supply, Distribution Systems, and Fixtures

# SHOWER DOOR BINDS AND OPERATES WITH EXCESSIVE NOISE.

MASTER BATHROOM Recommendation Contact a qualified professional.





5.1.3 A. Plumbing Supply, Distribution Systems, and Fixtures



## FLEXIBLE GAS PIPE ROUTED ACCROSS WALKWAY IN ATTIC.

Gas piping should be installed in a manor to prevent damage to pipe and tripping hazard.

Recommendation Contact a qualified professional.



6.1.1 A. Dishwashers

## **NO AIR GAP**



The dishwasher discharge (drain) line needs to be elevated above the inlet to disposal or drain pipe so that it has an air gap to prevent debris and gray water from draining down line from disposal or drain pipe and back into dishwasher.

Recommended DIY Project



