



General Information: Overview

A home inspection is a non-invasive, visual examination of the accessible areas of the property, designed to identify areas of concern within specific systems or components defined by the City Of Edmonton Standards of Practice, that are both observed and deemed material by the inspector at the exact date and time of inspection. Any and all recommendations for repair, replacement, evaluation, and maintenance issues found, should be evaluated by the appropriate trades contractors within the clients inspection contingency window or prior to closing, which is contract applicable, in order to obtain proper dollar amount estimates on the cost of said repairs and also because these evaluations could uncover more potential issues than able to be noted from a purely visual inspection of the property. This inspection will not reveal every concern or issue that exists, but only those material defects that were observable on the day of the inspection. This inspection is intended to assist an evaluation of the overall condition of the dwelling only. This inspection is not a prediction of future conditions and conditions with the property are subject to change the moment we leave the premises.

3.1.1 Siding, Flashing & Trim



CRACKING - MINOR

OUTSIDE GARAGE CORNER WALL

Loose sliding observed. This is a result of temperature changes, and typical as homes with stucco age. Recommend monitoring.

Recommended DIY Project



3.2.1 Exterior Doors

DOORBELL

FRONT DOOR

Observed doorbell not operational, Recommend Correction.



4.4.1 Wall Structure

CRACKS - MINOR

BASEMENT/GARAGE




Minor cracking was observed in the wall structure. This is common in homes. Recommend monitoring.

Recommendation

Contact a qualified professional.

InspecUs Page 1 of 8





Cracks are not visible in thermal images, which is cosmetic repair, recommended.Basement

EVIDENCE OF STRUCTURAL A IMMEDIATE/SAFETY ITEM **DAMAGE**



Evidence of structural repair was found in the ceiling structure. Recommend a structural engineer evaluate repair.

Recommendation

Contact a qualified structural engineer.



5.1.1 Equipment

NEEDS SERVICING/CLEANING



Furnace should be cleaned and serviced annually. Recommend a qualified HVAC contractor clean, service and certify furnace.

Here is a resource on the importance of furnace maintenance.

Recommendation

Contact a qualified HVAC professional.

InspecUs Page 2 of 8





6.2.1 Drain, Waste, & Vent Systems

IMPROPER CONNECTION



BASEMENT

loose connection and leak observed at a drain, waste pipe. Recommend a qualified plumber evaluate and repair.

Recommendation

Contact a qualified plumbing contractor.



6.4.1 Hot Water Systems, Controls, Flues & Vents

WATER STAINS - LEAKAGE

BASEMENT

Water stains were observed beneath water heater, indicating a past or present leak. Recommend further evaluation and repair by a qualified plumber.

Recommendation

Contact a qualified plumbing contractor.

6.4.2 Hot Water Systems, Controls, Flues & Vents

NOT OPERATIONAL


BASEMENT

Couldn't determine power source for operation, Recommend Contacting seller/condo management for its operational



operational.

InspecUs Page 3 of 8





6.6.1 Bathroom Fixture

SINK

MAIN FLOOR HALF BATHROOM









6.6.2 Bathroom Fixture

TOILET

2ND FLOOR ENSUITE BATHROOM

Loose fitting observed, Recommend Repair by qualified Professional.





InspecUs Page 4 of 8


6.7.1 Kitchen Fixture

SINK



MAIN FLOOR KITCHEN

Observed leak while operating kitchen Faucet, Recommend Repair by qualified professional.





7.2.1 Main & Subpanels, Service & Grounding, Main Overcurrent Device

Recommendation

MISSING LABELS ON PANEL

At the time of inspection, panel was missing labeling. Recommend a qualified electrician or person identify and map out locations.

Recommendation

Contact a qualified electrical contractor.





7.4.1 Lighting Fixtures, Switches & Receptacles

LIGHT INOPERABLE

EXTERIOR, LIVING ROOM, 2ND FLOOR

One or more lights are not operating. New light bulb possibly needed.

Recommendation

Contact a qualified electrical contractor.



InspecUs Page 5 of 8





7.5.1 GFCI & AFCI

NO GFCI PROTECTION INSTALLED



MAIN FLOOR HALF BATHROOM

No GFCI protection present in all locations. Recommend licensed electrician upgrade by installing ground fault receptacles in all locations.

Here is a link to read about how GFCI receptacles keep you safe.

Recommendation

Contact a qualified electrical contractor.



7.6.1 Smoke Detectors

RECOMMEND INSTALLATION



Recommend Installing Smoke Detector and CO2 Detector in basement and garage.

9.1.1 Doors

DOOR DOESN'T LATCH



2ND FLOOR BEDROOM

Door doesn't latch properly. Recommend handyman repair latch and/or strike plate.

Recommendation

Contact a qualified handyman.

InspecUs Page 6 of 8



9.1.2 Doors

DOOR KNOBS MISSING



Missing knobs in basement. Recommend Correction



11.1.1 Ceiling

DAMAGED



Garage ceiling was damaged. Recommend qualified contractor evaluate and repair.

Recommendation Contact a qualified professional.



Page 7 of 8 InspecUs

DAMAGE GARAGE TRIM



GARAGE

Observed Garage door' trim damage and missing cover plate to protect from deterioration.

Recommendation
Contact a qualified garage door contractor.





Page 8 of 8 InspecUs