INTEGRI-SPEC INSPECTIONS SUMMARY 1234 Main St.Winona MN 55987 Buyer Name 09/09/2018 9:00AM



2.3.1 Roof Drainage Systems UNDERGROUND DRAINAGE

🔑 Maintenance / Comment

Gutters drained underground. Recommend to monitor condition of drainage to ensure water discharges to exterior/daylight.

Recommendation Recommend monitoring.



3.2.1 Exterior Doors

WEATHERSTRIPPING NEEDS REPAIR

REAR

Door weatherstripping is in need of repair/replace. This can result in significant energy loss and moisture intrusion. Recommend repair/replacement of standard weatherstripping.Here is a DIY guide on weatherstripping.

Recommendation Contact a handyman or DIY project





3.3.1 Windows

MISSING SCREEN

Missing screen at multiple windows throughout the home.



5.2.1 Equipment 2 CORROSION

GARAGE 2


Furnace was corroded in one or more areas. This could be the result of leakage from the roof. Recommend a HVAC contractor and/or roofer evaluate and repair.

Recommendation

Contact a qualified HVAC professional.



5.6.1 Fireplaces ADD CO DETECTOR



LIVING ROOM Recommend to add carbon monoxide detector within the same room that the fireplace is located. Recommendation Contact a handyman or DIY project

5.6.2 Fireplaces ADD SMOKE ALARM



LIVING ROOM Recommend to add smoke detector within the same room that the fireplace is located. Recommendation Contact a handyman or DIY project

5.6.3 Fireplaces

SERVICING/CLEANING

NEEDS

Recommendation / Improvement

Fireplace should be cleaned and inspected prior to first use and not less than serviced annually.

Observed what appears to be some insulation within the flue as well as damper frame/hardware that appears to be corroded and may be in need of repair.



6.3.1 Distribution System **AC CONDENSATE LEAK**

The air conditioner condensate was leaking, recommend repair.

Recommendation Contact a qualified professional.



8.3.1 Main & Subpanels, Service & Grounding, Main Overcurrent Device



KNOCKOUTS MISSING

"Knockouts" are missing on the electric panel. This poses a safety hazard and it is recommended that the opening in the panel caused by the missing knockout(s) be properly sealed by a licensed electrician. Recommendation

Contact a qualified electrical contractor.





8.3.2 Main & Subpanels, Service & Grounding, Main Overcurrent Device

WATER IN ELECTRICAL PANEL

GARAGE 2

Observed water in the electrical panel. Recommend qualified electrical contractor review and provide evaluation of findings.

Recommendation




8.4.1 Branch Wiring Circuits, Breakers & Fuses

DOUBLE TAPPED HOT CONDUCTORS

Recommendation / Improvem

One or more electrical circuits were double tapped. This means that two or more wires are connected to a circuit breaker that is only designed to accept one wire. Recommend a qualified professional review and repair as necessary. Recommendation

Contact a qualified electrical contractor.







14.2.1 Plumbing & Fixtures
SINK - FAUCET LEAKS
1ST FLOOR BATHROOM 1
Faucet leaks at handle, recommend repair.
Recommendation
Contact a qualified professional.

Maintenance / Comment



14.2.2 Plumbing & Fixtures TUB - POOR DRAINAGE



1ST FLOOR BATHROOM 1

Tub had slow/poor drainage. Recommend a qualified plumber repair.

Recommendation Contact a qualified plumbing contractor.



14.2.3 Plumbing & Fixtures **TOILET - LOOSE BOWL**



1ST FLOOR BATHROOM 1

Toilet was not securely fastened to the floor. Recommend a qualified plumber repair. Recommendation Contact a qualified plumbing contractor.




14.3.1 Electrical & Other **BATHROOM GFCI UPGRADE**

1ST FLOOR BATHROOM 1

As a safety upgrade, recommend that the receptacle(s) be upgraded to GFCI receptacles.

Recommendation Contact a qualified electrical contractor.







15.3.1 Electrical & Other BATHROOM GFCI UPGRADE

BASEMENT BATHROOM 2

As a safety upgrade, recommend that the receptacle(s) be upgraded to GFCI receptacles.

Recommendation Contact a qualified electrical contractor.





15.3.2 Electrical & Other

EXHAUST FAN NOT PRESENT

Maintenance / Comment

BASEMENT BATHROOM 2

Bathroom exhaust vent was not present. As an upgrade recommend installing vent and exhaust to exterior. Recommendation Contact a qualified professional.



Maintenance / Comment

17.1.1 General COUNTERTOP NOT SECURED

KITCHEN

Kitchen countertop appeared insecure. Recommend to secure properly.

Recommendation Contact a handyman or DIY project



17.2.1 Plumbing & Fixtures
FAUCET LEAKS

KITCHEN

Kitchen Faucet leaks at handle. Recommendation Contact a qualified professional. Maintenance / Comment

Integri-Spec LLC



17.3.1 Electrical & Other **KITCHEN GFCI UPGRADE** KITCHEN

Maintenance / Comment

As a safety upgrade, recommend that the receptacle(s) be upgraded to GFCI receptacles. Recommendation Contact a qualified electrical contractor.

