

2.1.1 A. Foundations

WATER PENETRATION

UNDER STAIRS STORAGE AREA

Crawl/storage space under the interior staircase show signs of water penetration.





2.2.1 B. Grading and Drainage

NEGATIVE GRADING

EAST SIDE OF HOUSE

Negative grading on the east side of building

Recommendation









Recommendation

2.11.2 K. Porches, Balconies, Decks, and Carports

PATIO AT REAR OF HOUSE HAS NO GUARDRAIL.

Decks 30 inches above grade are required to have a guardrail.

Recommendation


Contact a qualified deck contractor.



4.3.1 C. Duct System, Chases, and Vents

TEMPERATURE DIFFERENTIAL

ATTIC



Recommendation

Contact a qualified HVAC professional.

