



1.3.1 Structure Details

CHANGE LOCKS

Ohana Inspections recommends that ALL locks and Security codes be changed before moving into the house.

Recommended DIY Project

2.1.1 Coverings

PONDING

Observed ponding in one or more areas of roof. Ponding can lead to accelerated erosion and deterioration. Recommend a qualified roofing contractor evaluate and repair.

Recommendation

Contact a qualified roofing professional.





2.1.2 Coverings

TILES CRACKED/BROKEN AND MISSING

Roof had cracked/broken tiles. Inspector recommends a licensed roofing contractor repair or replace to prevent moisture intrusion and/or mold.

Recommendation

Contact a qualified roofing professional.







Ohana Inspections Page 1 of 19



2.2.1 Roof Drainage Systems

DEBRIS

Debris has accumulated in the gutters. Recommend cleaning to facilitate water flow.

Here is a DIY resource for cleaning your gutters.

Recommendation

Contact a qualified roofing professional.



2.2.2 Roof Drainage Systems

GUTTER LEAKAGE

Gutters were observed to be leaking in one or more areas. This can result in excessive moisture in the soil at the foundation, which can lead to foundation/structural movement. Recommend a qualified contractor evaluate and repair gutters to proper functionality.

Recommendation

Contact a qualified roofing professional.

Ohana Inspections Page 2 of 19





2.4.1 Skylights, Chimneys & Other Roof Penetrations

VENT STACK BOOT

Vent stack boot was not properly placed. Inspector recommends hammering down the inner edges a little further.

Recommendation Contact a qualified professional.





3.1.1 Siding, Flashing & Trim

CRACKING - MINOR

Siding showed cracking in one or more places. This is a result of temperature changes, and typical as homes with stucco age. Stucco cracking is not a normal symptom of a new construction home. Recommend repair and monitoring.

Recommendation Recommended DIY Project







Ohana Inspections Page 3 of 19



3.1.2 Siding, Flashing & Trim

EVIDENCE OF WATER INTRUSION

Siding showed signs of water intrusion. This could lead to further siding deterioration and/or mold. Recommend a qualified siding contractor evaluate and repair.

Recommendation Contact a qualified professional.



Ohana Inspections Page 4 of 19







3.1.3 Siding, Flashing & Trim MISSING TRIM Recommendation Contact a qualified professional.



3.1.4 Siding, Flashing & Trim SIDING IN NEED OF REPAIR

Multiple areas of siding in need of repair. Inspector recommends hiring a siding contractor to evaluate the siding condition and determine extent of repair.

Recommendation Contact a qualified professional.



Ohana Inspections Page 5 of 19

3.2.1 Exterior Doors

DOOR SILL/TRIM

Door sill and/or trim is loose, deteriorated or worn and repair or replacement should be considered.

Recommendation

Contact a qualified door repair/installation contractor.







3.2.2 Exterior Doors

PAINT/REFINISH NEEDED

Door finish is worn. Recommend refinish and/or paint to maximize service life.

Here is a DIY article on refinishing a wood door.

Recommendation

Contact a qualified door repair/installation contractor.



3.3.1 Walkways, Patios & Driveways

WALKWAY TRIP HAZARD

Trip hazards observed. Patch or repair recommended.

Recommendation

Contact a qualified professional.



3.4.1 Decks, Balconies, Porches & Steps

PATIO TILES CRACKED

Recommendation

Contact a qualified professional.



Ohana Inspections Page 6 of 19

3.6.1 Vegetation, Grading, Drainage & Retaining Walls

TREE OVERHANG

Trees observed overhanging the roof. This can cause damage to the roof and prevent proper drainage. Recommend a qualified tree service trim to allow for proper drainage.

Recommendation

Contact a qualified tree service company.







4.3.1 Electrical

COVER PLATE MISSING

Cover plate(s) are missing from one or more electric boxes, such as for receptacles, switches and/or junction boxes. They are intended to contain fire and prevent electric shock from exposed wires. This is a safety hazard due to the risk of fire and shock. Cover plates should be installed where missing.

Recommendation

Contact a qualified electrical contractor.



5.1.1 Cooling Equipment

INSULATION MISSING OR DAMAGED

Missing or damaged insulation on refrigerant line can cause energy loss and condensation.

Recommendation

Contact a qualified HVAC professional.







5.2.1 Normal Operating Controls

FLOAT SWITCH NOT IN PLACE

Ohana Inspections Page 7 of 19

Recommendation Contact a qualified professional.



6.1.1 Main Water Shut-off Device

MINOR LEAK

Minor leak comming from spicket at house main shut off.

Recommendation

Contact a qualified professional.



6.3.1 Water Supply, Distribution Systems & Fixtures

TOILET LOOSE

Toilet is loose at the base. Recommend a qualified plumber evaluate and repair to prevent further water damage.

Recommendation

Contact a qualified plumbing contractor.





6.3.2 Water Supply, Distribution Systems & Fixtures

POLYBUTYLENE SUPPLY PIPES

Water supply pipes for master bathroom toilet only were made from polybutylene material. This material can be prone to fail without warning, causing damage to the home structure. Recommend a qualified plumber replace pipes and fittings with an approved material like PEX.

You can read more about polybutylene piping here and here.

Recommendation

Contact a qualified plumbing contractor.



Ohana Inspections Page 8 of 19

6.3.3 Water Supply, Distribution Systems & Fixtures

WATER STOP DAMAGED

Recommendation Contact a qualified professional.



6.3.4 Water Supply, Distribution Systems & Fixtures

LEAK UNDER SINK

Leak detected under bathroom sink. Inspector recommends hiring a qualified plumbing professional to repair. Monitor for possible mold growth.

Recommendation

Contact a qualified plumbing contractor.



6.3.5 Water Supply, Distribution Systems & Fixtures

LOOSE WATER FIXTURE

Handle on master bathroom tub and sink were not properly attached. Recommend repair.

Recommendation

Contact a qualified professional.





6.3.6 Water Supply, Distribution Systems & Fixtures

FLEX PIPE

Flexible drain pipe was installed under sinks. Inspector recommends they be replaced with smooth PVC to avoid build up and unpleasant odors.

Recommendation

Contact a qualified professional.



6.3.7 Water Supply, Distribution Systems & Fixtures

SLOW DRAIN

Ohana Inspections Page 9 of 19

One of the sinks in the master bathroom was slow to drain.

Recommendation Contact a qualified professional.





6.3.8 Water Supply, Distribution Systems & Fixtures

BATHTUB ACCESS COVER OPEN

Inspector recommends locking to avoid unwanted guests.

Recommendation Contact a qualified professional.



6.3.9 Water Supply, Distribution Systems & Fixtures

BATHTUB HOSE NOT FUNCTIONAL

Recommendation

Contact a qualified professional.



6.4.1 Hot Water Systems, Controls, Flues & Vents

CORROSION

Corrosion was noted at the burn chamber or pipe fittings. Recommend a qualified plumber evaluate for repair/replacement. Recommendation

Contact a qualified plumbing contractor.



6.5.1 Sprinkler System

SPRINKLER HEAD DAMAGE

Ohana Inspections Page 10 of 19

One or more sprinkler heads showed signs of damage at time of inspection.

Recommendation

Contact a qualified professional.

7.2.1 Main & Subpanels, Service & Grounding, Main Overcurrent Device

DOUBLE-TAP

In this sub-panel, two wires were connected to a breaker designed for only one wire. This is known as a "double-tap" and is a defective condition that should be corrected by a qualified electrical contractor.

Recommendation

Contact a qualified electrical contractor.



7.4.1 Lighting Fixtures, Switches & Receptacles

COVER PLATES DAMAGED

One or more receptacles have a damaged cover plate. Recommend replacement.

Recommendation

Contact a qualified electrical contractor.





7.5.1 GFCI & AFCI

GFCI NOT FUNCTIONAL

Recommendation

Contact a qualified professional.



7.7.1 External Components

EXPOSED WIRES

Recommendation

Contact a qualified electrical contractor.

Ohana Inspections Page 11 of 19



7.7.2 External Components

EXTERIOR LIGHT FIXTURE IN NEED OF REPAIR

Recommendation Contact a qualified professional.





7.7.3 External Components

MISSING COVER

Recommendation

Contact a qualified professional.





8.2.1 Windows

WINDOWS NEED CAULKING

Windows show signs of dry caulking recommend repair to prevent water intrusion.

Recommendation

Contact a qualified professional.

Ohana Inspections Page 12 of 19



8.2.2 Windows

HARDWARE DAMAGE

Locking mechanism was damaged at time of inspection.

Recommendation Contact a qualified professional.



8.2.3 Windows

WINDOWS IN NEED OF CLEANING

Recommendation Contact a qualified professional.

Ohana Inspections Page 13 of 19





8.2.4 Windows

WINDOW HARDWARE MISSING

Locking hardware foor master bedroom windows was not present at time of inspection.

Recommendation

Contact a qualified professional.







8.3.1 Floors

BASEBOARD DAMAGE

Recommendation Contact a qualified professional.



8.4.1 Walls


SHOWER NEEDS GROUT

Certain areas of the showers need more grout. Inspector recommends fixing immediately to avoid water damage.

Recommendation

Contact a qualified professional.

Ohana Inspections Page 14 of 19



8.5.1 Ceilings

CRACKS ON CEILING

Cracks were discovered on interior ceiling. This could be indication of water intrusion, structural issues, settlement or excess weight on trusses in the attic. Inspector recommends determining the cause of the cracking and evaluating for repairs.

Recommendation Contact a qualified professional.



Ohana Inspections Page 15 of 19



8.7.1 Countertops & Cabinets

POOR/MISSING CAULK

Bathroom shower and Kitchen ere missing sufficient caulk/sealant at the wall. This can lead to water damage. Recommend adding sealant at sides and corners where counters touch walls.

Here is a helpful DIY video on caulking gaps.

Recommendation Recommended DIY Project





9.6.1 Wine Cooler **BROKEN GLASS**Recommendation
Contact a qualified professional.



10.1.1 General

DRYER VENT COVER DAMAGE

This could permit unwanted guest to enter home.

Ohana Inspections Page 16 of 19

Recommendation Contact a qualified professional.





10.1.2 General

THE LAUNDRY CHUTE

Laundry Chute was a straight shot down. This could pose a potential fall risk for young children.

Recommendation Contact a qualified professional.





11.2.1 Fencing

NO FENCING

There were no holes showing around pool deck for fencing

Recommendation

Contact a qualified professional.





11.5.1 Pool and decking

TILE AND GROUT DETERIORATION

Ohana Inspections Page 17 of 19

Several of the tiles and grout around the pool and/or spa are deteriorated. The tiles and the grout should be repaired to help prevent water intrusion behind the tile work which can cause them to loosen up.

Recommendation

Contact a qualified Swimming Pool Contractor











11.5.2 Pool and decking

PAVERS NEED TO BE EVALUATED

Recommendation

Contact a qualified professional.





12.2.1 Garage Door

TRIM DAMAGE

Garage door trim showed signs of damage at time of inspection.

Recommendation

Contact a qualified professional.



Ohana Inspections Page 18 of 19

Ohana Inspections Page 19 of 19