

SUMMARY 1234 Main St.Richardson TX 75080 Buyer Name 04/28/2019 9:00AM



2.1.1 A. Foundations FOUNDATION CRACKS - MINOR



Minor cracking was noted at the foundation. This is common as concrete ages and shrinkage surface cracks are normal. Recommend monitoring for more serious shifting/displacement.

Here is an informational article on foundation cracks.

Recommendation

Contact a qualified structural engineer.



2.2.1 B. Grading and Drainage **DAMAGED GUTTER OR DOWNSPOUT**

Gutters or downspouts appear to be damaged. This could obstruct the flow of shedding water. Recommend having landscape experts evaluate and repair.

Recommendation Contact a qualified landscaping contractor





2.4.1 D. Roof Structures & Attics **POSSIBLE RODENT ENTRY**



Gaps in attic structure big enough to allow possible rodent entry.

Recommendation Contact a qualified handyman.



2.5.1 E. Walls (Interior and Exterior) **BROKEN/CRAKED SIDING**

All damage / cracked siding should be repaired or replaced in any crack seal to keep the integrity of the weather envelope provided by exterior wall coverings.

Recommendation Contact a qualified siding specialist.






2.5.2 E. Walls (Interior and Exterior) **GAPS AT EXTERIOR WALL**

Seal all gaps at joints and utility penetrations to prevent moisture and pest intrusion.

Recommendation Contact a qualified professional.







2.8.1 H. Windows **DAMAGED**

MASTER BEDROOM

One or more windows appears to have general damage, but are operational. Recommend a window professional clean, lubricate & adjust as necessary.

Recommendation Contact a qualified window repair/installation contractor.



2.8.2 H. Windows IMPROPER INSTALLATION

- Recommendation

2ND FLOOR PORCH WINDOWS

Windows appear to not be operating properly due to substandard installation. Recommend window specialist evaluate.

Recommendation Contact a qualified window repair/installation contractor.



3.2.1 B. Branch Circuits, Connected Devices, and Fixtures LIGHT INOPERABLE GAME ROOM

One or more lights are not operating. New light bulb possibly needed. Recommendation

Contact a qualified electrical contractor.





4.3.1 C. Duct System, Chases, and Vents **IMPROPER VENTING**

2ND FLOOR

One or more areas had improper or substandard venting, which can lead to inefficient heating/cooling. If room is intended for only storage please disregard.

Recommendation Contact a qualified professional.





4.3.2 C. Duct System, Chases, and Vents RETURN AIR SYSTEM MISSING/INSUFFICIENT

- Recommendation

DOWNSTAIRS OFFICE

Return air registers were missing or insufficient. This can result in poor heating efficiency. Recommend a qualified HVAC contractor evaluate and remedy.

Recommendation Contact a qualified HVAC professional.

6.5.1 E. Microwave Ovens IMPROPER INSTALLATION



Oven or microwave trim not flush. This is a brand new install. There is no reason at this time for trim not to be properly installed.

Recommendation Contact a qualified cabinet contractor.

