

## HOFFMAN HOME INSPECTION

316-202-8206 hoffmanhomeinspectionks@gmail.com http://www.HoffmanHomeInspection.com



# **RESIDENTIAL REPORT**

## 1234 Main St. Wichita Kansas 67216

Buyer Name 08/07/2017 9:00AM



Inspector Dale Hoffman 316-734-0772 benjamin@hoffmanhomeinspectionsteam.c



Agent Name 555-555-5555 agent@spectora.com

## **Table of Contents**

2
3
5
6
9
17
19
24
31
34
36
46
47
48

# SUMMARY



- Exterior Siding, Flashing & Trim: Damage Major
- Exterior Eaves, Soffits & Fascia: Eaves Damaged
- Exterior Vegetation, Grading, Drainage & Retaining Walls: Negative Grading
- Exterior Vegetation, Grading, Drainage & Retaining Walls: Tree Overhang
- □ Exterior Walkways, Patios & Driveways: Driveway Cracking Major
- □ Exterior Walkways, Patios & Driveways: Patio Settling Major
- □ Roofing Roof Drainage Systems: Debris
- □ Roofing Roof Drainage Systems: Downspouts Drain Near House
- Description Plumbing Fixtures / Faucets: Improper Installation
- Plumbing Water Heater: Annual Maintenance Flush Needed
- Plumbing Water Heater: Improper Installation
- Electrical Branch Circuit Conductors, Overcurrent Devices and Compatibility of Their Amperage & Voltage: Improper Wiring
- Electrical Connected Devices and Fixtures: Open Junction Box
- Electrical Polarity and Grounding of Receptacles: Outlet(s) Not Grounded
- Electrical Smoke Detectors: Smoke detectors Aged
- □ Heating Heating Equipment: Corrosion
- □ Heating Heating Equipment: Filter requires replacement
- □ Heating Heating Equipment: Manifolds dirty
- Heating Heating Equipment: Needs Servicing/Cleaning
- □ Interiors Walls: Minor Corner Cracks
- □ Interiors Ceilings: Minor Damage
- Interiors Ceilings: Possible Roof Leak Damage
- □ Interiors Floors: Damaged (General)
- □ Interiors Windows: Damaged
- □ Interiors Windows: Missing Hardware
- □ Fireplaces and Fuel-Burning Appliances Fireplaces, Stoves & Inserts: Firewall Cracked

#### Hoffman Home Inspection

# **1: INSPECTION DETAILS**

## Information

In Attendance Client, Client's Agent

**Temperature (approximate)** 82 Fahrenheit (F) Occupancy Furnished, Vacant

Type of Building Single Family Style Ranch

Weather Conditions Clear

# 2: STRUCTURAL COMPONENTS

3. STRUCTURAL COMPONENTS 3.1 The inspector shall: A. inspect structural components including the foundation and framing. B. describe: 1. the methods used to inspect under floor crawlspaces and attics. 2. the foundation. 3. the floor structure. 4. the wall structure. 5. the ceiling structure. 6. the roof structure. 3.2 The inspector is NOT required to: A. provide engineering or architectural services or analysis. B. offer an opinion about the adequacy of structural systems and components. C. enter under floor crawlspace areas that have less than 24 inches of vertical clearance between components and the ground or that have an access opening smaller than 16 inches by 24 inches. D. traverse attic load-bearing components that are concealed by insulation or by other materials.

## Information

#### **Inspection Method**

Crawlspace Access, Visual

Foundation, Basement & Crawlspaces: Material Concrete



Floor Structure: Material Wood I-Joists





Floor Structure: Sub-floor Plywood

Floor Structure: Basement/Crawlspace Floor Dirt Wall Structure: Material Wood

Ceiling Structure: Material Wood

		IN	NI	NP	R
2.1	Foundation, Basement & Crawlspaces	Х			
2.2	Floor Structure	Х			
2.3	Wall Structure	Х			
2.4	Ceiling Structure	Х			
2.5	Roof Structure & Attic		Х		
	IN = Inspected NI = Not Inspected NP = Not Present	R = Recommendations			ations

## Limitations

Roof Structure & Attic not inspected.

# **3: EXTERIOR**

4.1 The inspector shall: A. inspect: 1. wall coverings, flashing, and trim. 2. exterior doors. 3. attached and adjacent decks, balconies, stoops, steps, porches, and their associated railings. 4. eaves, soffits, and fascias where accessible from the ground level. 5. vegetation, grading, surface drainage, and retaining walls that are likely to adversely affect the building. 6. adjacent and entryway walkways, patios, and driveways. B. describe wall coverings. 4.2 The inspector is NOT required to inspect: A. screening, shutters, awnings, and similar seasonal accessories. B. fences, boundary walls, and similar structures. C. geological and soil conditions. D. recreational facilities. E. outbuildings other than garages and carports. F. seawalls, break-walls, and docks. G. erosion control and earth stabilization measures.

## Information

Inspection Method Visual	Siding, Flashing & Trim: Siding Material Vinyl	Siding, Flashing & Trim: Siding Style Panels
Exterior Doors: Exterior Entry	Decks, Balconies, Porches &	Decks, Balconies, Porches &
Door	Steps: Appurtenance	Steps: Material
Wood	Patio	Concrete

#### Walkways, Patios & Driveways: Driveway Material

Concrete

		IN	NI	NP	R
3.1	Siding, Flashing & Trim	Х			Х
3.2	Exterior Doors	Х			
3.3	Decks, Balconies, Porches & Steps	Х			
3.4	Eaves, Soffits & Fascia	Х			Х
3.5	Vegetation, Grading, Drainage & Retaining Walls	Х			Х
3.6	Walkways, Patios & Driveways	Х			Х

Hoffman Home Inspection

## **Recommendations**

## 3.1.1 Siding, Flashing & Trim DAMAGE - MAJOR

Moderate to major damage was observed at one or more points on the exterior. This can be the result of poor original compaction of soil at the time of construction or excess moisture in the underlying soil. Recommend consulting with a structural engineer and/or soil expert.

#### Recommendation

Contact a qualified siding specialist.




# EAVES - DAMAGED

One or more sections of the eaves are damaged. Recommend qualified roofer evaluate & repair.

#### Recommendation

Contact a qualified roofing professional.







## **Buyer Name**

3.5.1 Vegetation, Grading, Drainage & Retaining Walls

# NEGATIVE GRADING

Grading is sloping towards the home in some areas. This could lead to water intrusion and foundation issues. Recommend qualified landscaper or foundation contractor regrade so water flows away from home.

# Here is a helpful article discussing negative grading.

Recommendation Contact a qualified landscaper or gardener.



3.5.2 Vegetation, Grading, Drainage & Retaining Walls

# TREE OVERHANG

Trees observed overhanging the roof. This can cause damage to the roof and prevent proper drainage. Recommend a qualified tree service trim to allow for proper drainage.

#### Recommendation

Contact a qualified tree service company.



## Buyer Name

3.6.1 Walkways, Patios & Driveways

# DRIVEWAY CRACKING -MAJOR

Major cracks observed. Recommend driveway contractor evaluate and replace.

#### Recommendation

Contact a qualified driveway contractor.



3.6.2 Walkways, Patios & Driveways PATIO SETTLING -MAJOR

EAST

Significant settling observed. Further deterioration could result. Recommend concrete contractor evaluate & repair.

Recommendation

Contact a qualified concrete contractor.



# 4: ROOFING

5.1 The inspector shall: A. inspect: 1. roofing materials. 2. roof drainage systems. 3. flashing. 4. skylights, chimneys, and roof penetrations. B. describe: 1. roofing materials. 2. methods used to inspect the roofing. 5.2 The inspector is NOT required to inspect: A. antennas. B. interiors of vent systems, uses, and chimneys that are not readily accessible. C. other installed accessories.



#### **Inspection Method**

Aerial, Ladder

Roof Type/Style Gable Roof Drainage Systems: Gutter Material Vinyl

#### **Flashings: Material**

Aluminum

#### **Coverings: Material**

#### Rubber











#### **Buyer Name**

		IN	NI	NP	R
4.1	Coverings	Х			
4.2	Roof Drainage Systems	Х			Х
4.3	Flashings	Х			
4.4	Skylights, Chimneys & Roof Penetrations	Х			
	IN = Inspected NI = Not Inspected NP = Not Present R = Recommer				ations

## Recommendations

4.2.1 Roof Drainage Systems

## DEBRIS

Debris has accumulated in the gutters. Recommend cleaning to facilitate water flow.

Here is a DIY resource for cleaning your gutters.

Recommendation

Contact a qualified roofing professional.

4.2.2 Roof Drainage Systems

# DOWNSPOUTS DRAIN NEAR HOUSE

One or more downspouts drain too close to the home's foundation. This can result in excessive moisture in the soil at the foundation, which can lead to foundation/structural movement. Recommend a qualified contractor adjust downspout extensions to drain at least 6 feet from the foundation.

Here is a helpful DIY link and video on draining water flow away from your house.

Recommendation

Contact a qualified roofing professional.

# 5: PLUMBING

6.1 The inspector shall: A. inspect: 1. interior water supply and distribution systems including fixtures and faucets. 2. interior drain, waste, and vent systems including fixtures. 3. water heating equipment and hot water supply systems. 4. vent systems, flues, and chimneys. 5. fuel storage and fuel distribution systems. 6. sewage ejectors, sump pumps, and related piping. B. describe: 1. interior water supply, drain, waste, and vent piping materials. 2. water heating equipment including energy source(s). 3. location of main water and fuel shut-off valves. 6.2 The inspector is NOT required to: A. inspect: 1. clothes washing machine connections. 2. interiors of vent systems, flues, and chimneys that are not readily accessible. 3. wells, well pumps, and water storage related equipment. 4. water conditioning systems. 5. solar, geothermal, and other renewable energy water heating systems. 6. manual and automatic re-extinguishing and sprinkler systems and landscape irrigation systems. 7. septic and other sewage disposal systems. B. determine: 1. whether water supply and sewage disposal are public or private. 2. water quality. 3. the adequacy of combustion air components. C. measure water supply low and pressure, and well water quantity. D. fill shower pans and fixtures to test for leaks.

## Information

Filters None

Source

Public

#### Material - Distribution Galvanized

#### Water Heater: Manufacturer

Envirotemp



Material - Water Supply Unknown

Water Heater: Power Source Gas

## Water Heater:

40 Gallons There are no deficiencies found the hot water heater at



### Water Heater: Location

Utility Room



## Main Water Shut-Off Device (Location)

Crawlspace



## Drain, Waste, & Vent Systems: Drain Size





## Drain, Waste, & Vent Systems: Material



			IN	NI	NP	R
5.1	Fixtures / Faucets		Х			Х
5.2	Drain, Waste, & Vent Systems		Х			
5.3	Water Heater		Х			Х
5.4	Vents, Flues, & Chimneys		Х			Х
5.5	Sump Pumps / Sewage Ejectors				Х	
5.6	Fuel Storage & Distribution Systems		Х			
	IN = Inspected NI = Not Inspected	d NP = Not Present	R = Recommendation			ations

## Limitations

## Sump Pumps / Sewage Ejectors not present.

## **Recommendations**

5.1.1 Fixtures / Faucets IMPROPER INSTALLATION 1ST FLOOR HALL BATHROOM

Fixtures were installed improperly. Recommend a qualified handyman or plumber evaluate and repair.

Recommendation

Contact a quality handyman.



# 5.3.1 Water Heater ANNUAL MAINTENANCE FLUSH NEEDED

Water heaters should be flushed annually to prevent sediment buildup and maintain efficiency. Recommend a qualified plumber service and flush.

Here is a DIY link to help.

Recommendation Contact a qualified plumber. 5.3.2 Water Heater

## IMPROPER INSTALLATION Safety Hazard and/or Requires Immediate Attention

Water heater is improperly installed. Recommend qualified plumber evaluate & repair.

Recommendation Contact a qualified plumber.



# 6: ELECTRICAL

7.1 The inspector shall: A. inspect: 1. service drop. 2. service entrance conductors, cables, and raceways. 3. service equipment and main disconnects. 4. service grounding. 5. interior components of service panels and subpanels. 6. conductors. 7. overcurrent protection devices. 8. a representative number of installed lighting fixtures, switches, and receptacles. 9. ground fault circuit interrupters and arc fault circuit interrupters. B. describe: 1. amperage rating of the service. 2. location of main disconnect(s) and subpanels. 3. presence or absence of smoke alarms and carbon monoxide alarms. 4. the predominant branch circuit wiring method. 7.2 The inspector is NOT required to: A. inspect: 1. remote control devices. 2. or test smoke and carbon monoxide alarms, security systems, and other signaling and warning devices. 3. low voltage wiring systems and components. 4. ancillary wiring systems and components not a part of the primary electrical power distribution system. 5. solar, geothermal, wind, and other renewable energy systems. B. measure amperage, voltage, and impedance. C. determine the age and type of smoke alarms and carbon monoxide alarms.

## Information

Branch Wire 15 and 20 AMP Aluminum Wiring Method Romex



Service and Grounding Equipment, Main Overcurrent Device, Main and Distribution Panels: Panel Capacity 100 AMP

Service and Grounding Equipment, Main Overcurrent Device, Main and Distribution Panels: Panel Manufacturer Challenger, General Electric

## Service Entrance Conductors: Electrical Service Conductors

Overhead, 220 Volts, Aluminum



# Service and Grounding Equipment, Main Overcurrent Device, Main and Distribution Panels: Panel Locations

Exterior, Main Level









# Service and Grounding Equipment, Main Overcurrent Device, Main and Distribution Panels: Panel Type

**Circuit Breaker** 



		IN	NI	NP	R
6.1	Service Entrance Conductors	Х			
6.2	6.2 Service and Grounding Equipment, Main Overcurrent Device, Main and Distribution Panels				
6.3	Branch Circuit Conductors, Overcurrent Devices and Compatibility of Their Amperage & Voltage	Х			х
6.4	Connected Devices and Fixtures	Х			Х
6.5	Polarity and Grounding of Receptacles	Х			Х
6.6	GFCI & AFCI	Х			
6.7	Smoke Detectors	Х			Х
6.8	Carbon Monoxide Detectors			Х	
	IN = Inspected NI = Not Inspected NP = Not Present R = Recommendati				

## Limitations

Carbon Monoxide Detectors not present.

## **Recommendations**

6.3.1 Branch Circuit Conductors, Overcurrent Devices and Compatibility of Their Amperage & Voltage

## **IMPROPER WIRING**

A Safety Hazard and/or Requires Immediate Attention

Improper wiring was observed at the time of inspection. Recommend a licensed electrician evaluate and repair.

Recommendation Contact a qualified electrician.

6.4.1 Connected Devices and Fixtures **OPEN JUNCTION BOX** Safety Hazard and/or Requires Immediate Attention

Open junction box observed. Recommend concealing or replacing.

Recommendation Recommended DIY Project



6.5.1 Polarity and Grounding of Receptacles

# OUTLET(S) NOT GROUNDED

KITCHEN Safety Hazard and/or Requires Immediate Attention

One or more outlets are not grounded. Recommend a qualified electrician replace non-grounded outlets with grounded ones.

#### Recommendation

Contact a qualified electrician.





Smoke detectors appeared to have reached the end of the their useful life.

Recommendation

Contact a qualified appliance repair professional.

# 7: HEATING

8.1 The inspector shall: A. open readily openable access panels. B. inspect: 1. installed heating equipment. 2. vent systems, uses, and chimneys. 3. distribution systems. C. describe: 1. energy source(s). 2. heating systems. 8.2 The inspector is NOT required to: A. inspect: 1. interiors of vent systems, uses, and chimneys that are not readily accessible.
2. heat exchangers. 3. humidifiers and dehumidifiers. 4. electric air cleaning and sanitizing devices. 5. heating systems using ground-source, water-source, solar, and renewable energy technologies. 6. heat-recovery and similar whole-house mechanical ventilation systems. B. determine: 1. heat supply adequacy and distribution balance. 2. the adequacy of combustion air components.

### Information

# Heating Equipment: Filter Size

Heating Equipment: Filter Type Disposable Heating Equipment: Heat Type Forced Air

#### Heating Equipment: Brand

Comfort maker



## Heating Equipment: Energy Source

Gas



## Distribution Systems: Ductwork





		IN	NI	NP	R
7.1	Heating Equipment	Х			Х
7.2	Distribution Systems	Х			
7.3	Vents, Flues & Chimneys	Х			
-	IN = Inspected NI = Not Inspected NP = Not Pres	sent R=	Recor	nmend	ations

## Recommendations

7.1.1 Heating Equipment

## CORROSION

Furnace was corroded in one or more areas. This could be the result of improper venting, which the source would need to be identified. Recommend a HVAC contractor evaluate and repair.

Recommendation

Contact a qualified HVAC professional.

7.1.2 Heating Equipment

# FILTER REQUIRES REPLACEMENT

The furnace filter appears to be beyond its expected lifespan. Recommend replacement.

Recommendation Contact a qualified HVAC professional.

7.1.3 Heating Equipment
MANIFOLDS DIRTY

Cleaning manifolds will result in better air quality.

Recommendation Contact a qualified HVAC professional.

7.1.4 Heating Equipment

 NEEDS SERVICING/CLEANING

 A Safety Hazard and/or Requires Immediate Attention

Furnace should be cleaned and serviced annually. Recommend a qualified HVAC contractor clean, service and certify furnace.

Here is a resource on the importance of furnace maintenance.

Recommendation

Contact a qualified HVAC professional.

# 8: AIR CONDITIONING

9.1 The inspector shall: A. open readily openable access panels. B. inspect: 1. central and permanently installed cooling equipment. 2. distribution systems. C. describe: 1. energy source(s). 2. cooling systems. 9.2 The inspector is NOT required to: A. inspect electric air cleaning and sanitizing devices. B. determine cooling supply adequacy and distribution balance. C. inspect cooling units that are not permanently installed or that are installed in windows. D. inspect cooling systems using ground source, water source, solar, and renewable energy technologies.

## Information

#### Cooling Equipment: Brand

Goodman

Cooling Equipment: Energy Source/Type Electric Cooling Equipment: Location Exterior East

## Distribution System:

#### Configuration

Central

#### Туре

Air Conditioner

6	HOUSTON, TEXAS 77008
	MODEL CK30-18
	SERIAL NO. 9682127745
-	A.C. VOLTS _ 208/230 PHASE _ 1 HERTZ _ 60
	VOLTAGE RANGE MIN. 197 MAX. 253 4
	MIN. CIRCUIT AMPS 19.7
	MAX. FUSE AMPS OR HACR TYPE CIRCUIT BREAKER 38
	COMPRESSOR RLA 14.7 LRA 73.0
	MAX. WORKING PRESSURE
	FAN MOTOR FLA 1.3 H.P. 126
	FACTORY CHARGE OZ. R22 76
	(ED) , CAUTION: DISCONNECT THE ELECTRICAL POWER BEFORE SERVICING.
	CHARAN DISCONNECTER DU CIRCUIT D'ALIMENTATION ELECTRIQUE AVANT L'ENTRETIEN. USE COPPER CONDUCTORS ONLY.
	THIS EQUIPMENT SUITABLE FOR OUTDOOR, USE.
	CO181770080 CITY OF NEW YORK
	Generation Measurements Con. L.F. Manutan, YL 17800
	CENTRAL MEA NO. 193-93-E PART NO. 14936-56
	00182770080 (REV-A) B14930-00
	and the second states to present
the ?	

#### **Cooling Equipment: SEER Rating**

10

Modern standards call for at least 13 SEER rating for new install.

Read more on energy efficient air conditioning at Energy.gov.

		IN	NI	NP	R
8.1	Cooling Equipment	Х			
8.2	Distribution System	Х			

## Buyer Name

IN = Inspected NI = Not Inspected NP = Not Present R = Recommendations

# 9: INTERIORS

10.1 The inspector shall inspect: A. walls, ceilings, and floors. B. steps, stairways, and railings. C. countertops and a representative number of installed cabinets. D. a representative number of doors and windows. E. garage vehicle doors and garage vehicle door operators. F. installed ovens, ranges, surface cooking appliances, microwave ovens, dishwashing machines, and food waste grinders by using normal operating controls to activate the primary function. 10.2 The inspector is NOT required to inspect: A. paint, wallpaper, and other finish treatments. B. floor coverings. C. window treatments. D. coatings on and the hermetic seals between panes of window glass. E. central vacuum systems. F. recreational facilities. G. installed and free-standing kitchen and laundry appliances not listed in Section 10.1.F. H. appliance thermostats including their calibration, adequacy of heating elements, self cleaning oven cycles, indicator lights, door seals, timers, clocks, timed features, and other specialized features of the appliance. I. operate, or confirm the operation of every control and feature of an inspected appliance.

## Information

#### Walls: Wall Material



Ceilings: Ceiling Material Gypsum Board Floors: Floor Coverings Hardwood, Vinyl Some minor cracks in kitchen floor tiles replace or repair

#### Windows: Window Type

Sliders




Windows: Window Manufacturer Unknown

### 1234 Main St.

#### **Countertops & Cabinets: Countertop Material**

Kitchen 1st Floor Laminate Countertop is chipped









### 1234 Main St.

### **Countertops & Cabinets: Cabinetry**

Kitchen

Wood

Kitchen cabinetry shows normal wear and tear



		IN	NI	NP	R
9.1	Walls	Х			Х
9.2	Ceilings	Х			Х
9.3	Floors	Х			Х
9.4	Steps, Stairways & Railings	Х			
9.5	Countertops & Cabinets	Х			
9.6	Doors	Х			
9.7	Windows	Х			Х
9.8	Garage Door			Х	
9.9	Garage interior			Х	
	IN Increased NI Net Increased NIP Net Present P. Pacammendation				

IN = Inspected

NI = Not Inspected

NP = Not Present

Garage Door not present.

Garage interior not present.

**Recommendations** 

## 9.1.1 Walls MINOR CORNER CRACKS

Minor cracks at the corners of doors and windows in walls. Appeared to be the result of long-term settling. Some settling is not unusual in a home of this age and these cracks are not a structural concern.

#### Recommendation

Contact a qualified structural engineer.



1234 Main St.

# 9.2.1 Ceilings MINOR DAMAGE

Minor damage or deterioration to the ceiling was visible at the time of the inspection.

Recommendation

Contact a qualified professional.



### 9.2.2 Ceilings **POSSIBLE ROOF LEAK DAMAGE** ABOVE FRONT DOOR

Stains on the ceiling appear to be the result of roof leaks. The source of leakage should be identified and corrected, and the ceiling re-painted.

Recommendation Contact a qualified professional.




# 9.3.1 Floors DAMAGED (GENERAL)

The home flooring had general moderate damage visible at the time of the Hoffman Home Inspection

### Buyer Name

### 1234 Main St.

inspection. Recommend evaluation by a qualified flooring contractor.



## Buyer Name





# 9.7.1 Windows

One or more windows appears to have general damage, but are operational. Recommend a window professional clean, lubricate, seal & adjust as necessary.

#### Recommendation

Contact a qualified window repair/installation contractor.



# 9.7.2 Windows MISSING HARDWARE

Window missing hardware. Recommend replacement.

Recommendation

Contact a qualified window repair/installation contractor.



# **10: BUILT-IN APPLIANCES**

10.1 The inspector shall inspect: F. installed ovens, ranges, surface cooking appliances, microwave ovens, dishwashing machines, and food waste grinders by using normal operating controls to activate the primary function. 10.2 The inspector is NOT required to inspect: G. installed and free-standing kitchen and laundry appliances not listed in Section 10.1.F. H. appliance thermostats including their calibration, adequacy of heating elements, self cleaning oven cycles, indicator lights, door seals, timers, clocks, timed features, and other specialized features of the appliance. I. operate, or con rm the operation of every control and feature of an inspected appliance.

		IN	NI	NP	R
10.1	Dishwasher			Х	
10.2	Refrigerator			Х	
10.3	Range/Oven/Cooktop			Х	
10.4	Garbage Disposal	Х			
10.5	Microwave			Х	
10.6	Microwave			Х	
10.7	Trash compactor			Х	
	IN = Inspected NI = Not Inspected NP = Not Present	R = Recommendations			

### Limitations

Dishwasher not present.

Refrigerator not present.

Range/Oven/Cooktop not present.

Microwave not present.

Microwave not present.

Trash compactor not present.

# **11: INSULATION AND VENTILATION**

11.1 The inspector shall: A. inspect: 1. insulation and vapor retarders in unfinished spaces. 2. ventilation of attics and foundation areas. 3. kitchen, bathroom, laundry, and similar exhaust systems. 4. clothes dryer exhaust systems. B. describe: 1. insulation and vapor retarders in unfinished spaces. 2. absence of insulation in unfinished spaces at conditioned surfaces. 11.2 The inspector is NOT required to disturb insulation.

### Information

Dryer Power Source	Dryer Vent	Flooring Insulation
220 Electric	Metal (Flex)	None

		IN	NI	NP	R
11.1	Attic Insulation			Х	
11.2	Vapor Retarders			Х	
11.3	Ventilation			Х	
11.4	Exhaust Systems			Х	
	IN = Inspected NI = Not Inspected NP = Not Present	R = Recommendation			ations

### Limitations

Attic Insulation not present.

Vapor Retarders not present.

Ventilation not present.

Exhaust Systems not present.

# 12: FIREPLACES AND FUEL-BURNING APPLIANCES

12.1 The inspector shall: A. inspect: 1. fuel-burning replaces, stoves, and replace inserts. 2. fuel-burning accessories installed in replaces. 3. chimneys and vent systems. B. describe systems and components listed in 12.1.A.1 and .2. 12.2 The inspector is NOT required to: A. inspect: 1. interiors of vent systems, uses, and chimneys that are not readily accessible. 2. fire screens and doors. 3. seals and gaskets. 4. automatic fuel feed devices. 5. mantles and replace surrounds. 6. combustion air components and to determine their adequacy. 7. heat distribution assists (gravity fed and fan assisted). 8. fuel-burning replaces and appliances located outside the inspected structures. B. determine draft characteristics. C. move fireplace inserts and stoves or firebox contents.

### Information

## Туре

Wood

		IN	NI	NP	R
12.1	Fireplaces, Stoves & Inserts	Х			Х
12.2	Fuel-buring Accessories			Х	
12.3	Chimney & Vent Systems	Х			
	IN = Inspected NI = Not Inspected NP = Not Present	R = Recommendations			

### Limitations

Fuel-buring Accessories not present.

### **Recommendations**

### 12.1.1 Fireplaces, Stoves & Inserts **FIREWALL CRACKED** Safety Hazard and/or Requires Immediate Attention

The brick lining of the fireplace was cracked in one or more places, which could lead to chimney damage or toxic fumes entering the home. Recommend a qualified fireplace contractor evaluate and repair.

#### Recommendation

Contact a qualified fireplace contractor.

