



6168489401 inkhomeservices@gmail.com https://www.inkhomeservices.com



INSPECTION REPORT

1234 Main St. Grand Rapids MI 49503

Buyer Name 07/31/2017 9:00AM



Inspector
Daniel Geurink
InterNACHI Certified Home Inspector
616-848-9401
inkhomeservices@gmail.com



Agent Name 555-555-5555 agent@spectora.com

Table of Contents

Table of Contents	2
SUMMARY	3
1: INSPECTION DETAILS	5
2: ROOF	6
3: EXTERIOR	9
4: BASEMENT, FOUNDATION, CRAWLSPACE & STRUCTURE	19
5: HEATING	23
6: COOLING	26
7: PLUMBING	29
8: ELECTRICAL	34
9: ATTIC, INSULATION & VENTILATION	39
10: DOORS, WINDOWS & INTERIOR	42
11: BUILT-IN APPLIANCES	49

Ink Home Services Page 2 of 51

SUMMARY



24

SAFETY HAZARDS 8

RECOMMENDATIONS

SAFETY HAZARDS & IMMEDIATE ATTENTION ITEMS

Roof - Coverings: Improper/Incomplete Nailing
Exterior - Siding, Flashing & Trim: Flashing/Trim Improperly Installed
Exterior - Siding, Flashing & Trim: Dryer Vent
Exterior - Siding, Flashing & Trim: Small Localized Damage
Exterior - Exterior Doors: Door Does Not Close or Latch
Exterior - Walkways, Patios & Driveways: Driveway Cracking - Minor
Exterior - Decks, Balconies, Porches & Steps: Deck - Water Sealant Required
Exterior - Decks, Balconies, Porches & Steps: Railing Unsafe/Missing
Exterior - Vegetation, Grading, Drainage & Retaining Walls: Negative Grading
Exterior - Vegetation, Grading, Drainage & Retaining Walls: Loose Retaining wall
Basement, Foundation, Crawlspace & Structure - Floor Structure: Evidence of Water Intrusion
Basement, Foundation, Crawlspace & Structure - Garage Structure: Evidence of Water Intrusion
Heating - Equipment: Needs Servicing/Cleaning
Heating - Equipment: Possible Heat Exchanger Issue
Cooling - Cooling Equipment: Vegetation Too Close
Cooling - Cooling Equipment: Unit Undersized
Plumbing - Drain, Waste, & Vent Systems: Leaking Pipe
Plumbing - Drain, Waste, & Vent Systems: Toilet
Plumbing - Hot Water Systems, Controls, Flues & Vents: Improper Installation
Electrical - Branch Wiring Circuits, Breakers & Fuses: Improper Wiring
Electrical - Smoke Detectors: Low Battery
Electrical - Carbon Monoxide Detectors: Missing
Doors, Windows & Interior - Doors: Water Staining
Doors, Windows & Interior - Floors: Carpet Stains
Doors, Windows & Interior - Floors: Moderate Wear
Doors, Windows & Interior - Walls: Minor Corner Cracks
Doors, Windows & Interior - Ceilings: Stain(s) on Ceiling

Ink Home Services Page 3 of 51

1234 Main St.

□ Doors, Windows & Interior - Ceilings: Fan
□ Doors, Windows & Interior - Countertops & Cabinets: Cabinets Damaged

Doors, Windows & Interior - Countertops & Cabinets: Countertop Cracked/Chipped
 Built-in Appliances - Refrigerator: Dents

Ink Home Services Page 4 of 51

1: INSPECTION DETAILS

Information

In Attendance

Client, Client's Agent

Type of Building

Detached, Single Family

Occupancy

Furnished, Occupied

Weather Conditions

Clear

Temperature

73 Fahrenheit (F)

Ink Home Services Page 5 of 51

2: ROOF

I. The inspector shall inspect from ground level or the eaves: A. the roof-covering materials; B. the gutters; C. the downspouts; D. the vents, flashing, skylights, chimney, and other roof penetrations; and E. the general structure of the roof from the readily accessible panels, doors or stairs. II. The inspector shall describe: A. the type of roof-covering materials. III. The inspector shall report as in need of correction: A. observed indications of active roof leaks. IV. The inspector is not required to: A. walk on any roof surface. B. predict the service life expectancy. C. inspect underground downspout diverter drainage pipes. D. remove snow, ice, debris or other conditions that prohibit the observation of the roof surfaces. E. move insulation. F. inspect antennae, satellite dishes, lightning arresters, de-icing equipment, or similar attachments. G. walk on any roof areas that appear, in the inspector's opinion, to be unsafe. H. walk on any roof areas if doing so might, in the inspector's opinion, cause damage. I. perform a water test. J. warrant or certify the roof. K. confirm proper fastening or installation of any roof-covering material.

Information

Inspection Method

Ladder, Roof

Roof Type/Style
Combination

Flashings: Material


Aluminum

Coverings: Material

Asphalt







Ink Home Services Page 6 of 51

Gutters: Gutter Material

Aluminum, Seamless Aluminum





		IN	NI	NP	R
2.1	Coverings	Χ			Χ
2.2	Gutters	Χ			
2.3	Flashings	Χ			
2.4	Skylights, Chimneys & Other Roof Penetrations	Χ			

IN = Inspected NI = Not Inspected NP = Not Present R = Recommendations

Recommendations

Ink Home Services Page 7 of 51

2.1.1 Coverings

IMPROPER/INCOMPLET E NAILING

Roof coverings showed signs of improper installation and fastening. Recommend a qualified roofing contractor evaluate and repair.

Recommendation

Contact a qualified roofing professional.





Ink Home Services Page 8 of 51

3: EXTERIOR

I. The inspector shall inspect: A. the exterior wall-covering materials, flashing and trim; B. all exterior doors; C. adjacent walkways and driveways; D. stairs, steps, stoops, stairways and ramps; E. porches, patios, decks, balconies and carports; F. railings, guards and handrails; G. the eaves, soffits and fascia; H. a representative number of windows; and I. vegetation, surface drainage, retaining walls and grading of the property, where they may adversely affect the structure due to moisture intrusion. II. The inspector shall describe: A. the type of exterior wall-covering materials. III. The inspector shall report as in need of correction: A. any improper spacing between intermediate balusters, spindles and rails. IV. The inspector is not required to: A. inspect or operate screens, storm windows, shutters, awnings, fences, outbuildings, or exterior accent lighting. B. inspect items that are not visible or readily accessible from the ground, including window and door flashing. C. inspect or identify geological, geotechnical, hydrological or soil conditions. D. inspect recreational facilities or playground equipment. E. inspect seawalls, breakwalls or docks. F. inspect erosion-control or earth-stabilization measures. G. inspect for safety-type glass. H. inspect underground utilities. I. inspect underground items. J. inspect wells or springs. K. inspect solar, wind or geothermal systems. L. inspect swimming pools or spas. M. inspect wastewater treatment systems, septic systems or cesspools. N. inspect irrigation or sprinkler systems. O. inspect drainfields or dry wells. P. determine the integrity of multiple-pane window glazing or thermal window seals.

Information

Exterior Doors: Garage Door

Inspection Method

Visual







Ink Home Services Page 9 of 51

Siding, Flashing & Trim: Siding Material

Vinyl



Exterior Doors: Exterior Entry Door

Glass, Steel



Ink Home Services Page 10 of 51

Walkways, Patios & Driveways: Driveway Material

Concrete, Cobblestone





Walkways, Patios & Driveways: Sidewalk Material

Concrete



Ink Home Services Page 11 of 51

Decks, Balconies, Porches & Steps: Material

Wood



		IN	NI	NP	R
3.1	Siding, Flashing & Trim	Χ			Χ
3.2	Exterior Doors	Χ			Χ
3.3	Walkways, Patios & Driveways	Χ			Χ
3.4	Decks, Balconies, Porches & Steps	Χ			Χ
3.5	Eaves, Soffits & Fascia	Χ			
3.6	Vegetation, Grading, Drainage & Retaining Walls	Χ			Χ

IN = Inspected NI = Not Inspected NP = Not Present R = Recommendations

Recommendations

Ink Home Services Page 12 of 51

3.1.1 Siding, Flashing & Trim

FLASHING/TRIM IMPROPERLY INSTALLED

Flashing & trim pieces were improperly installed, which could result in moisture intrusion and damaging leaks. Recommend a qualified siding contractor evaluate and repair.

Recommendation

Contact a qualified professional.



3.1.2 Siding, Flashing & Trim

DRYER VENT

Dryer vent in need of repair or replacement

Recommendation

Contact a qualified professional.



Ink Home Services Page 13 of 51

3.1.3 Siding, Flashing & Trim

SMALL LOCALIZED DAMAGE

There was on or more areas with small localized damage to the exterior siding

Recommendation

Contact a qualified professional.





Ink Home Services Page 14 of 51

3.2.1 Exterior Doors

DOOR DOES NOT CLOSE OR LATCH

Garage door does not close or latch properly. Recommend qualified handyman adjust door so that top left corner closes.

Recommendation

Contact a qualified door repair/installation contractor.



3.3.1 Walkways, Patios & Driveways

DRIVEWAY CRACKING - MINOR

Minor cosmetic cracks observed, which may indicate movement in the soil. Recommend monitor and/or have concrete contractor patch/seal.

Recommendation

Contact a qualified concrete contractor.



Ink Home Services Page 15 of 51

3.4.1 Decks, Balconies, Porches & Steps

DECK - WATER SEALANT REQUIRED

Deck is showing signs of weathering and/or water damage. Recommend water sealant/weatherproofing be applied.

Here is a helpful article on staining & sealing your deck.

Recommendation

Recommended DIY Project

3.4.2 Decks, Balconies, Porches & Steps

RAILING UNSAFE/MISSING

Attention Safety Hazard and/or Requires Immediate

There was one or more areas with 3 steps or more that had an unsafe or missing railing. This is a safety concern and should be addressed by a qualified contractor.

Railings on deck were wobbly and should be properly secured.

Recommendation

Contact a qualified carpenter.



Ink Home Services Page 16 of 51





Ink Home Services Page 17 of 51

3.6.1 Vegetation, Grading, Drainage & Retaining Walls

NEGATIVE GRADING

Grading is sloping towards the home in some areas. This could lead to water intrusion and foundation issues.

Recommend qualified landscaper or foundation contractor regrade so water flows away from home.

Here is a helpful article discussing negative grading.

Recommendation

Contact a qualified landscaper or gardener.



3.6.2 Vegetation, Grading, Drainage & Retaining Walls

LOOSE RETAINING WALL

Wooden retaining wall was loose at the time of inspection. Repair or replace with proper retaining wall.

Recommendation

Contact a qualified professional.



Ink Home Services Page 18 of 51

4: BASEMENT, FOUNDATION, CRAWLSPACE & STRUCTURE

I. The inspector shall inspect: A. the foundation; B. the basement; C. the crawlspace; and D. structural components. II. The inspector shall describe: A. the type of foundation; and B. the location of the access to the under-floor space. III. The inspector shall report as in need of correction: A. observed indications of wood in contact with or near soil; B. observed indications of active water penetration; C. observed indications of possible foundation movement, such as sheetrock cracks, brick cracks, out-of-square door frames, and unlevel floors; and D. any observed cutting, notching and boring of framing members that may, in the inspector's opinion, present a structural or safety concern. IV. The inspector is not required to: A. enter any crawlspace that is not readily accessible, or where entry could cause damage or pose a hazard to him/herself. B. move stored items or debris. C. operate sump pumps with inaccessible floats. D. identify the size, spacing, span or location or determine the adequacy of foundation bolting, bracing, joists, joist spans or support systems. E. provide any engineering or architectural service. F. report on the adequacy of any structural system or component.

Information

Floor Structure: Sub-floor

OSB

Floor Structure:

Basement/CrawIspace Floor

Concrete

Inspection Method


Visual



Ink Home Services Page 19 of 51

Foundation: Material

Concrete



Floor Structure: Material

Wood I-Joists





		IN	NI	NP	R
4.1	Foundation	Χ			
4.2	Basements & Crawlspaces	Χ			
4.3	Floor Structure	Χ			Х
4.4	Wall Structure	Χ			
4.5	Ceiling Structure	Χ			
4.6	Garage Structure	Χ			Х

IN = Inspected NI = Not Inspected NP = Not Present R = Recommendations

Recommendations

Ink Home Services Page 20 of 51

4.3.1 Floor Structure

EVIDENCE OF WATER INTRUSION

Attention Safety Hazard and/or Requires Immediate

There were signs of water intrusion in the underlying floor structure. Recommend identifying source of moisture and repairing.

Recommendation

Contact a qualified professional.



4.6.1 Garage Structure

EVIDENCE OF WATER INTRUSION

GARAGE

Attention Safety Hazard and/or Requires Immediate

Wall structure showed signs of previous water intrusion, which if not properly fixed could lead to more serious structural damage. Recommend a qualified contractor identify source or moisture and remedy.

Note: this may have already been repaired but since there has not been recent rain it is hard to tell.

Recommendation

Contact a qualified roofing professional.



Ink Home Services Page 21 of 51





Ink Home Services Page 22 of 51

5: HEATING

I. The inspector shall inspect: A. the heating system, using normal operating controls. II. The inspector shall describe: A. the location of the thermostat for the heating system; B. the energy source; and C. the heating method. III. The inspector shall report as in need of correction: A. any heating system that did not operate; and B. if the heating system was deemed inaccessible. IV. The inspector is not required to: A. inspect or evaluate the interior of flues or chimneys, fire chambers, heat exchangers, combustion air systems, fresh-air intakes, humidifiers, dehumidifiers, electronic air filters, geothermal systems, or solar heating systems. B. inspect fuel tanks or underground or concealed fuel supply systems. C. determine the uniformity, temperature, flow, balance, distribution, size, capacity, BTU, or supply adequacy of the heating system. D. light or ignite pilot flames. E. activate heating, heat pump systems, or other heating systems when ambient temperatures or other circumstances are not conducive to safe operation or may damage the equipment. F. override electronic thermostats. G. evaluate fuel quality. H. verify thermostat calibration, heat anticipation, or automatic setbacks, timers, programs or clocks.

Information


Equipment: Energy Source Equipment: Heat Type Equipment: Year


Natural Gas Gas-Fired Heat, Steam Boiler 2002 - 2004

AFUE Rating

80

AFUE (Annual fuel utilization efficiency) is a metric used to measure furnace efficiency in converting fuel to energy. A higher AFUE rating means greater energy efficiency. 90% or higher meets the Department of Energy's Energy Star program standard.





Ink Home Services Page 23 of 51

Equipment: Brand

Carrier





Distribution Systems: Ductwork

Non-insulated



		IN	NI	NP	R
5.1	Equipment	Χ			Χ
5.2	Normal Operating Controls	Χ			
5.3	Distribution Systems	Χ			
5.4	Vents, Flues & Chimneys	Χ			
5.5	Gas/LP Firelogs & Fireplaces		Χ		
5.6	Presence of Installed Heat Source in Each Room	Χ			

IN = Inspected NI = Not Inspected NP = Not Present R = Recommendations

Limitations

Ink Home Services Page 24 of 51

Gas/LP Firelogs & Fireplaces

FIREPLACE DOOR

Fireplace door was zip tied shut

Recommendations

5.1.1 Equipment

NEEDS SERVICING/CLEANING

Furnace should be cleaned and serviced annually. Recommend a qualified HVAC contractor clean, service and certify furnace.

Here is a resource on the importance of furnace maintenance.

Recommendation

Contact a qualified HVAC professional.

5.1.2 Equipment

POSSIBLE HEAT EXCHANGER ISSUE

Attention Safety Hazard and/or Requires Immediate

The burner flame on the furnace was flickering yellow during inspection. This can sometimes be a result of an issue with the heat exchanger. It is recommended to have the furnace fully inspected by an HVAC professional to determine whether the furnace is just burning inefficiently or if there are heat exchanger issues present

Recommendation

Contact a qualified HVAC professional.



Ink Home Services Page 25 of 51

6: COOLING

I. The inspector shall inspect: A. the cooling system, using normal operating controls. II. The inspector shall describe: A. the location of the thermostat for the cooling system; and B. the cooling method. III. The inspector shall report as in need of correction: A. any cooling system that did not operate; and B. if the cooling system was deemed inaccessible. IV. The inspector is not required to: A. determine the uniformity, temperature, flow, balance, distribution, size, capacity, BTU, or supply adequacy of the cooling system. B. inspect portable window units, through-wall units, or electronic air filters. C. operate equipment or systems if the exterior temperature is below 65° Fahrenheit, or when other circumstances are not conducive to safe operation or may damage the equipment. D. inspect or determine thermostat calibration, cooling anticipation, or automatic setbacks or clocks. E. examine electrical current, coolant fluids or gases, or coolant leakage.

Information

Cooling Equipment: Energy

Source/Type

Electric

Cooling Equipment: Location

Exterior East

Cooling Equipment: Brand

Unknown





Cooling Equipment: SEER Rating

12 SEER

Modern standards call for at least 13 SEER rating for new install.

Read more on energy efficient air conditioning at Energy.gov.

Ink Home Services Page 26 of 51

Distribution System: Configuration

Central



		IN	NI	NP	R
6.1	Cooling Equipment	Χ			Χ
6.2	Normal Operating Controls	Χ			
6.3	Distribution System	Χ			
6.4	Presence of Installed Cooling Source in Each Room	Χ			

IN = Inspected NI = Not Inspected NP = Not Present R = Recommendations

Recommendations

Ink Home Services Page 27 of 51

6.1.1 Cooling Equipment

VEGETATION TOO CLOSE

Vegetation was too close to the compressor, which can limit heat dissipation and limit effectiveness.

Recommend cutting back vegetation to avoid overheating compressor.

Recommendation

Recommended DIY Project



6.1.2 Cooling Equipment

UNIT UNDERSIZED

Unit appears to be to small for the home size. A proper cooling load calculation should be used to determine the correct size of the unit.

Recommendation

Contact a qualified HVAC professional.



Ink Home Services Page 28 of 51

7: PLUMBING

I. The inspector shall inspect: A. the main water supply shut-off valve; B. the main fuel supply shut-off valve; C. the water heating equipment, including the energy source, venting connections, temperature/pressure-relief (TPR) valves, Watts 210 valves, and seismic bracing; D. interior water supply, including all fixtures and faucets, by running the water; E. all toilets for proper operation by flushing; F. all sinks, tubs and showers for functional drainage; G. the drain, waste and vent system; and H. drainage sump pumps with accessible floats. II. The inspector shall describe: A. whether the water supply is public or private based upon observed evidence; B. the location of the main water supply shut-off valve; C. the location of the main fuel supply shut-off valve; D. the location of any observed fuel-storage system; and E. the capacity of the water heating equipment, if labeled. III. The inspector shall report as in need of correction: A. deficiencies in the water supply by viewing the functional flow in two fixtures operated simultaneously; B. deficiencies in the installation of hot and cold water faucets; C. mechanical drain stops that were missing or did not operate if installed in sinks, lavatories and tubs; and D, toilets that were damaged, had loose connections to the floor, were leaking, or had tank components that did not operate. IV. The inspector is not required to: A. light or ignite pilot flames. B. measure the capacity, temperature, age, life expectancy or adequacy of the water heater. C. inspect the interior of flues or chimneys, combustion air systems, water softener or filtering systems, well pumps or tanks, safety or shut-off valves, floor drains, lawn sprinkler systems, or fire sprinkler systems. D. determine the exact flow rate, volume, pressure, temperature or adequacy of the water supply. E. determine the water quality, potability or reliability of the water supply or source. F. open sealed plumbing access panels. G. inspect clothes washing machines or their connections. H. operate any valve. I. test shower pans, tub and shower surrounds or enclosures for leakage or functional overflow protection. J. evaluate the compliance with conservation, energy or building standards, or the proper design or sizing of any water, waste or venting components, fixtures or piping. K. determine the effectiveness of anti-siphon, backflow prevention or drain-stop devices. L. determine whether there are sufficient cleanouts for effective cleaning of drains. M. evaluate fuel storage tanks or supply systems. N. inspect wastewater treatment systems. O. inspect water treatment systems or water filters. P. inspect water storage tanks, pressure pumps, or bladder tanks. Q. evaluate wait time to obtain hot water at fixtures, or perform testing of any kind to water heater elements. R. evaluate or determine the adequacy of combustion air. S. test, operate, open or close: safety controls, manual stop valves, temperature/pressure-relief valves, control valves, or check valves. T. examine ancillary or auxiliary systems or components, such as, but not limited to, those related to solar water heating and hot water circulation. U. determine the existence or condition of polybutylene plumbing. V. inspect or test for gas or fuel leaks, or indications thereof.


Information

Filters None	Water Source Public	Drain, Waste, & Vent Systems: Drain Size 2"
Drain, Waste, & Vent Systems: Material ABS	Water Supply, Distribution Systems & Fixtures: Water Supply Material Copper	Hot Water Systems, Controls, Flues & Vents: Power Source/Type Gas
Hot Water Systems, Controls, Flues & Vents: Capacity 40 gallons	Hot Water Systems, Controls, Flues & Vents: Location Basement	Fuel Storage & Distribution Systems: Main Gas Shut-off Location At Tank

Ink Home Services Page 29 of 51

Main Water Shut-off Device: Location

Basement



Water Supply, Distribution Systems & Fixtures: Distribution Material Copper



Ink Home Services Page 30 of 51

Hot Water Systems, Controls, Flues & Vents: Manufacturer

Richmond

I recommend flushing & servicing your water heater tank annually for optimal performance. Water temperature should be set to at least 120 degrees F to kill microbes and no higher than 130 degrees F to prevent scalding.

Here is a nice maintenance guide from Lowe's to help.





Sump Pump: Location

Basement



		IN	NI	NP	R
7.1	Main Water Shut-off Device	Χ			
7.2	Drain, Waste, & Vent Systems	Χ			Х
7.3	Water Supply, Distribution Systems & Fixtures	Χ			
7.4	Hot Water Systems, Controls, Flues & Vents	Χ			Х
7.5	Fuel Storage & Distribution Systems	Χ			
7.6	Sump Pump	Χ			

Ink Home Services Page 31 of 51

Recommendations

7.2.1 Drain, Waste, & Vent Systems

LEAKING PIPE

A drain, waste and/or vent pipe showed signs of a leak. Recommend a qualified plumber evaluate and repair.

Recommendation

Contact a qualified plumber.





Ink Home Services Page 32 of 51

7.2.2 Drain, Waste, & Vent Systems

TOILET

Toilet mechanism sticks when flushed. Should be repaired or replaced.

Recommendation

Contact a qualified plumber.



7.4.1 Hot Water Systems, Controls, Flues & Vents

IMPROPER INSTALLATION

Attention Safety Hazard and/or Requires Immediate

Water heater flue was improperly installed. It should go up a 1/4 inch per foot. Recommend qualified plumber evaluate & repair/relocate.

Recommendation

Contact a qualified plumber.



Ink Home Services Page 33 of 51

8: ELECTRICAL

I. The inspector shall inspect: A. the service drop; B. the overhead service conductors and attachment point; C. the service head, gooseneck and drip loops; D. the service mast, service conduit and raceway; E. the electric meter and base; F. service-entrance conductors; G. the main service disconnect; H. panelboards and over-current protection devices (circuit breakers and fuses); I. service grounding and bonding; J. a representative number of switches, lighting fixtures and receptacles, including receptacles observed and deemed to be arc-fault circuit interrupter (AFCI)-protected using the AFCI test button, where possible; K. all ground-fault circuit interrupter receptacles and circuit breakers observed and deemed to be GFCIs using a GFCI tester, where possible; and L. smoke and carbon-monoxide detectors. II. The inspector shall describe: A. the main service disconnect's amperage rating, if labeled; and B. the type of wiring observed. III. The inspector shall report as in need of correction: A. deficiencies in the integrity of the serviceentrance conductors' insulation, drip loop, and vertical clearances from grade and roofs; B. any unused circuit-breaker panel opening that was not filled; C. the presence of solid conductor aluminum branch-circuit wiring, if readily visible; D. any tested receptacle in which power was not present, polarity was incorrect, the cover was not in place, the GFCI devices were not properly installed or did not operate properly, evidence of arcing or excessive heat, and where the receptacle was not grounded or was not secured to the wall; and E. the absence of smoke detectors. IV. The inspector is not required to: A. insert any tool, probe or device into the main panelboard, sub-panels, distribution panelboards, or electrical fixtures. B. operate electrical systems that are shut down. C. remove panelboard cabinet covers or dead fronts. D. operate or re-set overcurrent protection devices or overload devices. E. operate or test smoke or carbon-monoxide detectors or alarms F. inspect, operate or test any security, fire or alarms systems or components, or other warning or signaling systems. G. measure or determine the amperage or voltage of the main service equipment, if not visibly labeled. H. inspect ancillary wiring or remote-control devices. I. activate any electrical systems or branch circuits that are not energized. J. inspect lowvoltage systems, electrical de-icing tapes, swimming pool wiring, or any timecontrolled devices. K. verify the service ground. L. inspect private or emergency electrical supply sources, including, but not limited to: generators, windmills, photovoltaic solar collectors, or battery or electrical storage facility. M. inspect spark or lightning arrestors. N. inspect or test de-icing equipment. O. conduct voltage-drop calculations. P. determine the accuracy of labeling. Q. inspect exterior lighting.

Information

Service Entrance Conductors: Electrical Service Conductors

Overhead, 220 Volts

Main & Subpanels, Service & Grounding, Main Overcurrent Device: Sub Panel Location

None

Main & Subpanels, Service & Grounding, Main Overcurrent Device: Panel Manufacturer Siemens, Crouse-Hinds

Branch Wiring Circuits, Breakers & Fuses: Wiring

Method Romex Main & Subpanels, Service & Grounding, Main Overcurrent Device: Panel Type

Circuit Breaker

Ink Home Services Page 34 of 51

Main & Subpanels, Service & Grounding, Main Overcurrent Device: Main Panel Location



Main & Subpanels, Service & Grounding, Main Overcurrent Device: Panel Capacity 100 AMP



Ink Home Services Page 35 of 51

Branch Wiring Circuits, Breakers & Fuses: Branch Wire 15 and 20 AMP

Copper



		IN	NI	NP	R
8.1	Service Entrance Conductors	Χ			
8.2	Main & Subpanels, Service & Grounding, Main Overcurrent Device	Χ			
8.3	Branch Wiring Circuits, Breakers & Fuses	Χ			Χ
8.4	Lighting Fixtures, Switches & Receptacles	Χ			
8.5	GFCI & AFCI	Χ			
8.6	Smoke Detectors	Χ			Χ
8.7	Carbon Monoxide Detectors	Χ			Χ

IN = Inspected NI = Not Inspected NP = Not Present R = Recommendations

Recommendations

Ink Home Services Page 36 of 51

8.3.1 Branch Wiring Circuits, Breakers & Fuses

IMPROPER WIRING

Light and fan controls are switched

Recommendation

Contact a qualified electrician.



8.6.1 Smoke Detectors

LOW BATTERY

Attention Safety Hazard and/or Requires Immediate

Smoke detector failed to respond when tested. Recommend battery be replaced.

Recommendation

Recommended DIY Project



Ink Home Services Page 37 of 51

8.7.1 Carbon Monoxide Detectors

MISSING



▲ Safety Hazard and/or Requires Immediate Attention

Carbon Monoxide detector was missing form one or more locations. Recommend installation of at least one low level CO monitor per floor.

Recommendation

Contact a qualified professional.

Ink Home Services Page 38 of 51

9: ATTIC, INSULATION & VENTILATION

I. The inspector shall inspect: A. insulation in unfinished spaces, including attics, crawlspaces and foundation areas; B. ventilation of unfinished spaces, including attics, crawlspaces and foundation areas; and C. mechanical exhaust systems in the kitchen, bathrooms and laundry area. II. The inspector shall describe: A. the type of insulation observed; and B. the approximate average depth of insulation observed at the unfinished attic floor area or roof structure. III. The inspector shall report as in need of correction: A. the general absence of insulation or ventilation in unfinished spaces. IV. The inspector is not required to: A. enter the attic or any unfinished spaces that are not readily accessible, or where entry could cause damage or, in the inspector's opinion, pose a safety hazard. B. move, touch or disturb insulation. C. move, touch or disturb vapor retarders. D. break or otherwise damage the surface finish or weather seal on or around access panels or covers. E. identify the composition or R-value of insulation material. F. activate thermostatically operated fans. G. determine the types of materials used in insulation or wrapping of pipes, ducts, jackets, boilers or wiring. H. determine the adequacy of ventilation.

Information

Dryer Power Source

Dryer Vent Metal (Flex) **Flooring Insulation**

None

Exhaust Systems: Exhaust

Fans

Gas

Fan with Light

Attic Insulation: R-value

30



Ink Home Services Page 39 of 51

Attic Insulation: Insulation Type

Cellulose, Blown



Ventilation: Ventilation Type



		IN	NI	NP	R
9.1	Attic Insulation	Χ			
9.2	Vapor Retarders (Crawlspace or Basement)			Χ	
9.3	Ventilation	Χ			
9.4	Exhaust Systems	Χ			
9.5	Wall Insulation	Χ			

IN = Inspected NI = Not Inspected NP = Not Present R = Recommendations

Limitations

Vapor Retarders (Crawlspace or Basement) not present.

Ink Home Services Page 40 of 51

Ink Home Services Page 41 of 51

10: DOORS, WINDOWS & INTERIOR

I. The inspector shall inspect: A. a representative number of doors and windows by opening and closing them; B. floors, walls and ceilings; C. stairs, steps, landings, stairways and ramps; D. railings, guards and handrails; and E. garage vehicle doors and the operation of garage vehicle door openers, using normal operating controls. II. The inspector shall describe: A. a garage vehicle door as manually-operated or installed with a garage door opener. III. The inspector shall report as in need of correction: A. improper spacing between intermediate balusters, spindles and rails for steps, stairways, guards and railings; B. photo-electric safety sensors that did not operate properly; and C. any window that was obviously fogged or displayed other evidence of broken seals. IV. The inspector is not required to: A. inspect paint, wallpaper, window treatments or finish treatments. B. inspect floor coverings or carpeting. C. inspect central vacuum systems. D. inspect for safety glazing. E. inspect security systems or components. F. evaluate the fastening of islands, countertops, cabinets, sink tops or fixtures. G. move furniture, stored items, or any coverings, such as carpets or rugs, in order to inspect the concealed floor structure. H. move suspended-ceiling tiles. I. inspect or move any household appliances. J. inspect or operate equipment housed in the garage, except as otherwise noted. K. verify or certify the proper operation of any pressure-activated auto-reverse or related safety feature of a garage door. L. operate or evaluate any security bar release and opening mechanisms, whether interior or exterior, including their compliance with local, state or federal standards. M. operate any system, appliance or component that requires the use of special keys, codes, combinations or devices. N. operate or evaluate self-cleaning oven cycles, tilt guards/latches, or signal lights. O. inspect microwave ovens or test leakage from microwave ovens. P. operate or examine any sauna, steamgenerating equipment, kiln, toaster, ice maker, coffee maker, can opener, bread warmer, blender, instant hot-water dispenser, or other small, ancillary appliances or devices. Q. inspect elevators. R. inspect remote controls. S. inspect appliances. T. inspect items not permanently installed. U. discover firewall compromises. V. inspect pools, spas or fountains. W. determine the adequacy of whirlpool or spa jets, water force, or bubble effects. X. determine the structural integrity or leakage of pools or spas.

Information

Windows: Window Type

Double-hung, Single-hung,

Sliders

Countertops & Cabinets:

Cabinetry

Wood

Ceilings: Ceiling Material

Gypsum Board

Countertops & Cabinets: Countertop Material

Laminate

Ink Home Services Page 42 of 51

Floors: Floor Coverings


Carpet, Vinyl, Laminate





Walls: Wall Material

Drywall



		IN	NI	NP	R
10.1	Doors	Χ			Χ
10.2	Windows	Χ			
10.3	Floors	Χ			Х
10.4	Walls	Χ			Χ
10.5	Ceilings	Χ			Х
10.6	Steps, Stairways & Railings	Χ			
10.7	Countertops & Cabinets	Χ			Х

IN = Inspected NI = Not Inspected NP = Not Present R = Recommendations

Recommendations

Ink Home Services Page 43 of 51

10.1.1 Doors

WATER STAINING

Door shows noticeable water staining, which could lead to further deterioration. Monitor for future repair or replacement.

Recommendation

Contact a quality handyman.



10.3.1 Floors

CARPET STAINS

Carpet had areas of staining or discoloration. Recommend a thorough steam clean by a qualified carpet cleaning company

Recommendation

Contact a qualified cleaning service.




Ink Home Services Page 44 of 51

10.3.2 Floors

MODERATE WEAR

Floors in the home exhibited moderate surface wear along major paths of travel. Recommend a qualified flooring contractor evaluate for possible re-finish.





Ink Home Services Page 45 of 51

10.4.1 Walls

MINOR CORNER CRACKS

Minor cracks at the corners of doors and windows in walls. Appeared to be the result of long-term settling. Some settling is not unusual in a home of this age and these cracks are not a structural concern.

Recommendation

Contact a qualified professional.



10.5.1 Ceilings

STAIN(S) ON CEILING

There is a stain on ceiling/wall that requires repair and paint. Source of staining should be determined and ceiling repainted.

Recommendation

Contact a qualified professional.



Ink Home Services Page 46 of 51


10.5.2 Ceilings

FAN

One or more fans were not working and in need of service at the time of the inspection. Repair or replace.

Recommendation

Contact a qualified electrician.



10.7.1 Countertops & Cabinets

CABINETS DAMAGED

Cabinets had visible damage at time of inspection. Recommend a qualified cabinets contractor evaluate and repair.

Recommendation

Contact a qualified cabinet contractor.



Ink Home Services Page 47 of 51

10.7.2 Countertops & Cabinets

COUNTERTOP CRACKED/CHIPPED

Countertop had one or more cracks or chips. Recommend qualified countertop contractor evaluate and repair.

Here is a helpful article on repairing cracks, chips & fissures.

Recommendation

Contact a qualified countertop contractor.



Ink Home Services Page 48 of 51

11: BUILT-IN APPLIANCES

10.1 The inspector shall inspect: F. installed ovens, ranges, surface cooking appliances, microwave ovens, dishwashing machines, and food waste grinders by using normal operating controls to activate the primary function. 10.2 The inspector is NOT required to inspect: G. installed and free-standing kitchen and laundry appliances not listed in Section 10.1.F. H. appliance thermostats including their calibration, adequacy of heating elements, self cleaning oven cycles, indicator lights, door seals, timers, clocks, timed features, and other specialized features of the appliance. I. operate, or con rm the operation of every control and feature of an inspected appliance.

Information

Range/Oven/Cooktop: Range/Oven Energy Source

Gas

Dishwasher: Brand

Bosch



Ink Home Services Page 49 of 51

Refrigerator: Brand

Amana



Range/Oven/Cooktop: Range/Oven Brand

Samsung



Ink Home Services Page 50 of 51

Range/Oven/Cooktop: Exhaust Hood Type

Re-circulate



		IN	NI	NP	R
11.1	Dishwasher	Χ			
11.2	Refrigerator	Χ			Χ
11.3	Range/Oven/Cooktop	Χ			
11.4	Garbage Disposal	Χ			

Recommendations

11.2.1 Refrigerator

DENTS

At the time of inspection the fridge had one or more dings dents or scratches. This did not appear to affect the functionality of the refridgerator.

Recommendation

Contact a qualified appliance repair professional.

Ink Home Services Page 51 of 51