

2.1.1 Coverings

SHINGLES MISSING

 Recommendation

ROOF

Observed two individual roofing shingles that are missing. Recommend a qualified roofing contractor evaluate & repair.

Recommendation
Contact a qualified roofing professional.



Missing Shingle (Rear Side of Roof)



Missing Shingle (Front Side of Roof)

8.4.1 Lighting Fixtures, Switches & Receptacles

LIGHT INOPERABLE

 Recommendation

MASTER BEDROOM CLOSET

Closet light in the master bedroom not operating. New light bulb possibly needed.

Recommendation
Contact a qualified electrical contractor.



Inoperable Closet Light