DETAILS SUMMARY

1234 Main St. Washougal Wa 98671 **Buyer Name** 06/19/2019 9:00AM

5.2.1 Walls, Firewalls and Ceiling FIREWALL DAMAGED/MISSING

Firewall separating the home and garage is not compliant with modern building standards. Firewalls should be built with materials to prevent the spreading of a fire into the home living space. Recommend a gualified contractor evaluate and bring firewall up to standards.

Link for more info.

Recommendation Contact a qualified professional.

5.4.1 Garage Door Opener AUTO REVERSE SENSOR NOT FUNCTIONING

The auto reverse sensor was not responding at time of inspection. This is a safety hazard to children and pets. Recommend a qualified garage door contractor evaluate and repair/replace.

Recommendation Contact a qualified professional.

10.7.1 Shower/Tub area MOISTURE

Floor appears to have moisture, possible leaks, recommend licensed contractor re-evaluate/repair as needed.

Recommendation Contact a qualified professional.







Safety Hazard



Safety Hazard

12.1.1 Basements & Crawlspaces **RODENT EVIDENCE**

- Major Concerns

There is visible evidence of past rodent/pest activity in crawlspace. The activity may or may not be currently active, however no current activity was visible at the time of inspection. Recommend licensed rodent/pest contractor re-evaluate.

Recommendation Contact a qualified professional.



15.1.1 Cooling Equipment IMPROPERLY SIZED BREAKERS

A/C unit, Improperly sized breakers, recommend repair.

Recommendation Contact a qualified professional.





16.2.1 Attic ATTIC, PLUMBING VENT LEAKING, RECOMMEND REPAIR



Attic, plumbing vent leaking, recommend repair

Recommendation Contact a qualified professional.

