RECOMMENDATIONS SUMMA



1234 Main St.Grand Rapids MI 49503 Buyer Name Daniel Geurink InterNACHI Certified Home Inspector Ink Home Services 616-848-9401 inkhomeservices@gmail.com




2.1.1 Coverings IMPROPER/INCOMPLETE NAILING

07/31/2017 9:00AM

Roof coverings showed signs of improper installation and fastening. Recommend a qualified roofing contractor evaluate and repair.

Recommendation Contact a qualified roofing professional.



3.1.1 Siding, Flashing & Trim FLASHING/TRIM IMPROPERLY INSTALLED

Flashing & trim pieces were improperly installed, which could result in moisture intrusion and damaging leaks. Recommend a qualified siding contractor evaluate and repair.

Recommendation Contact a qualified professional.



3.1.2 Siding, Flashing & Trim **DRYER VENT**

Dryer vent in need of repair or replacement

Recommendation Contact a qualified professional.



3.1.3 Siding, Flashing & Trim SMALL LOCALIZED DAMAGE

There was on or more areas with small localized damage to the exterior siding

Recommendation Contact a qualified professional.



3.2.1 Exterior Doors DOOR DOES NOT CLOSE OR LATCH

Garage door does not close or latch properly. Recommend qualified handyman adjust door so that top left corner closes.

Recommendation

Contact a qualified door repair/installation contractor.



3.3.1 Walkways, Patios & Driveways DRIVEWAY CRACKING - MINOR

Minor cosmetic cracks observed, which may indicate movement in the soil. Recommend monitor and/or have concrete contractor patch/seal.

Recommendation Contact a qualified concrete contractor.



3.4.1 Decks, Balconies, Porches & Steps DECK - WATER SEALANT REQUIRED

Deck is showing signs of weathering and/or water damage. Recommend water sealant/weatherproofing be applied.

Here is a helpful article on staining & sealing your deck.

Recommendation Recommended DIY Project

3.4.2 Decks, Balconies, Porches & Steps **RAILING UNSAFE/MISSING**

A Safety Hazard and/or Requires Immediate Attention

There was one or more areas with 3 steps or more that had an unsafe or missing railing. This is a safety concern and should be addressed by a qualified contractor.

Railings on deck were wobbly and should be properly secured.

Recommendation Contact a qualified carpenter.



3.6.1 Vegetation, Grading, Drainage & Retaining Walls

NEGATIVE GRADING

Grading is sloping towards the home in some areas. This could lead to water intrusion and foundation issues. Recommend qualified landscaper or foundation contractor regrade so water flows away from home.

Here is a helpful article discussing negative grading.

Recommendation Contact a qualified landscaper or gardener.

3.6.2 Vegetation, Grading, Drainage & Retaining Walls

Wooden retaining wall was loose at the time of inspection. Repair or replace with proper retaining wall.

Recommendation Contact a qualified professional.





4.3.1 Floor Structure

EVIDENCE OF WATER

A Safety Hazard and/or Requires Immediate Attention

There were signs of water intrusion in the underlying floor structure. Recommend identifying source of moisture and repairing.

Recommendation Contact a qualified professional.




4.6.1 Garage Structure EVIDENCE OF WATER INTRUSION GARAGE

Safety Hazard and/or Requires Immediate Attention

Wall structure showed signs of previous water intrusion, which if not properly fixed could lead to more serious structural damage. Recommend a qualified contractor identify source or moisture and remedy.

Note: this may have already been repaired but since there has not been recent rain it is hard to tell.

Recommendation Contact a qualified roofing professional.



5.1.1 Equipment NEEDS SERVICING/CLEANING

Furnace should be cleaned and serviced annually. Recommend a qualified HVAC contractor clean, service and certify furnace.

Here is a resource on the importance of furnace maintenance.

Recommendation Contact a qualified HVAC professional.

5.1.2 Equipment POSSIBLE HEAT EXCHANGER ISSUE

A Safety Hazard and/or Requires Immediate Attention

The burner flame on the furnace was flickering yellow during inspection. This can sometimes be a result of an issue with the heat exchanger. It is recommended to have the furnace fully inspected by an HVAC professional to determine whether the furnace is just burning inefficiently or if there are heat exchanger issues present

Recommendation Contact a qualified HVAC professional.



6.1.1 Cooling Equipment VEGETATION TOO CLOSE

Vegetation was too close to the compressor, which can limit heat dissipation and limit effectiveness. Recommend cutting back vegetation to avoid overheating compressor.

Recommendation Recommended DIY Project



6.1.2 Cooling Equipment UNIT UNDERSIZED

Unit appears to be to small for the home size. A proper cooling load calculation should be used to determine the correct size of the unit.

Recommendation Contact a qualified HVAC professional.



7.2.1 Drain, Waste, & Vent Systems

LEAKING PIPE

A drain, waste and/or vent pipe showed signs of a leak. Recommend a qualified plumber evaluate and repair.

Recommendation Contact a qualified plumber.



7.2.2 Drain, Waste, & Vent Systems



Toilet mechanism sticks when flushed. Should be repaired or replaced.

Recommendation Contact a qualified plumber.



7.4.1 Hot Water Systems, Controls, Flues & Vents

A Safety Hazard and/or Requires Immediate Attention

Water heater flue was improperly installed. It should go up a 1/4 inch per foot. Recommend qualified plumber evaluate & repair/relocate.

Recommendation Contact a qualified plumber.



8.3.1 Branch Wiring Circuits, Breakers & Fuses

IMPROPER WIRING

Light and fan controls are switched

Recommendation Contact a qualified electrician.



8.6.1 Smoke Detectors

LOW BATTERY

A Safety Hazard and/or Requires Immediate Attention

Smoke detector failed to respond when tested. Recommend battery be replaced.

Recommendation Recommended DIY Project



8.7.1 Carbon Monoxide Detectors MISSING Safety Hazard and/or Requires Immediate Attention

Carbon Monoxide detector was missing form one or more locations. Recommend installation of at least one low level CO monitor per floor.

Recommendation Contact a qualified professional.

10.1.1 Doors WATER STAINING

Door shows noticeable water staining, which could lead to further deterioration. Monitor for future repair or replacement.

Recommendation Contact a quality handyman.



10.3.1 Floors CARPET STAINS

Carpet had areas of staining or discoloration. Recommend a thorough steam clean by a qualified carpet cleaning company

Recommendation Contact a qualified cleaning service.



10.3.2 Floors MODERATE WEAR

Floors in the home exhibited moderate surface wear along major paths of travel. Recommend a qualified flooring contractor evaluate for possible re-finish.



10.4.1 Walls MINOR CORNER CRACKS

Minor cracks at the corners of doors and windows in walls. Appeared to be the result of long-term settling. Some settling is not unusual in a home of this age and these cracks are not a structural concern.

Recommendation Contact a qualified professional.



10.5.1 Ceilings STAIN(S) ON CEILING

There is a stain on ceiling/wall that requires repair and paint. Source of staining should be determined and ceiling repainted.

Recommendation Contact a qualified professional.



10.5.2 Ceilings

FAN

One or more fans were not working and in need of service at the time of the inspection. Repair or replace.

Recommendation Contact a qualified electrician.



10.7.1 Countertops & Cabinets

CABINETS DAMAGED

Cabinets had visible damage at time of inspection. Recommend a qualified cabinets contractor evaluate and repair.

Recommendation Contact a qualified cabinet contractor.



10.7.2 Countertops & Cabinets

COUNTERTOP CRACKED/CHIPPED

Countertop had one or more cracks or chips. Recommend qualified countertop contractor evaluate and repair.

Here is a helpful article on repairing cracks, chips & fissures.

Recommendation Contact a qualified countertop contractor.



11.2.1 Refrigerator

DENTS

At the time of inspection the fridge had one or more dings dents or scratches. This did not appear to affect the functionality of the refridgerator.

Recommendation Contact a qualified appliance repair professional.