

# Radon Inspection Report

## Measurement of Radon Concentration in Indoor Air

Report nr: 2700007263201904210748  
Serial nr: 2700007263

Report generated date: 4/21/19 7:48 AM

**Measurement Address:**

123 Main St  
Pearisburg, Virginia 24134  
United States

**Measurement performed by:**

John Heubi

thatplacehomeinspections@gmail.com

Ventilation: Natural

Building type: House

Building year: 2002

Room	Floor	Measurement Start	Measurement End	Measured Value
Living room	Basement	4/18/19 8:24 AM	4/20/19 8:24 AM	6.1 pCi/L



123 Main  
Location

April 21, 2019  
Date

Signature


# Detailed Measurement Data

Units	Min	Max	Average
Radon [pCi/L]	2.7	11.5	6.1
Temperature [°F]	66.9	73.0	70.9
Humidity [%rH]	47	48	47
Pressure [kPa]	92.53	94.39	93.29


## Radon measurements for hour 1 to hour 48

Hour	Radon [pCi/L]	Hour	Radon [pCi/L]	Hour	Radon [pCi/L]
4/18/19 8:24 AM	4.5	4/19/19 12:24 AM	5.9	4/19/19 4:24 PM	9.0
4/18/19 9:24 AM	2.7	4/19/19 1:24 AM	4.9	4/19/19 5:24 PM	11.5
4/18/19 10:24 AM	5.1	4/19/19 2:24 AM	4.3	4/19/19 6:24 PM	7.1
4/18/19 11:24 AM	4.8	4/19/19 3:24 AM	5.2	4/19/19 7:24 PM	6.2
4/18/19 12:24 PM	7.3	4/19/19 4:24 AM	2.8	4/19/19 8:24 PM	8.3
4/18/19 1:24 PM	6.9	4/19/19 5:24 AM	5.2	4/19/19 9:24 PM	6.1
4/18/19 2:24 PM	5.4	4/19/19 6:24 AM	4.3	4/19/19 10:24 PM	7.4
4/18/19 3:24 PM	7.3	4/19/19 7:24 AM	4.9	4/19/19 11:24 PM	7.9
4/18/19 4:24 PM	6.1	4/19/19 8:24 AM	3.9	4/20/19 12:24 AM	8.8
4/18/19 5:24 PM	6.5	4/19/19 9:24 AM	7.0	4/20/19 1:24 AM	6.9
4/18/19 6:24 PM	6.5	4/19/19 10:24 AM	4.9	4/20/19 2:24 AM	7.9
4/18/19 7:24 PM	5.9	4/19/19 11:24 AM	4.3	4/20/19 3:24 AM	5.7
4/18/19 8:24 PM	6.5	4/19/19 12:24 PM	5.5	4/20/19 4:24 AM	6.9
4/18/19 9:24 PM	5.2	4/19/19 1:24 PM	6.5	4/20/19 5:24 AM	8.1
4/18/19 10:24 PM	4.3	4/19/19 2:24 PM	5.9	4/20/19 6:24 AM	7.2
4/18/19 11:24 PM	5.5	4/19/19 3:24 PM	6.8	4/20/19 7:24 AM	7.2

# Radon Chart



# Humidity and Temperature Chart



# Pressure Chart

