



Site Address:

4512 Settlers Ranch
Colorado Springs, CO-80908

Inspection Date:

May 09, 2019

Report Prepared For:

Bill Price

Report Prepared By:

A Precise Home Inspection, Inc
7620 Pebble Path Pl
Colorado Springs, CO-80920
Phone Number: 719-466-1335

Inspector:

#N/A

Continuous Radon Monitor

Model Number: 1029
 Calibration Date: 12/31/2018
 Monitor Time: 5/9/2019 19:32

Serial Number: 85128007
 CF: 2.50, 2.53

Inspection Company

A Precise Home Inspection, Inc
 7620 Pebble Path Pl
 Colorado Springs, CO-80920
 Phone Number: 719-466-1335
 License Number: N/A

Billing Information

Bill Price
 4512 Settlers Ranch
 Colorado Springs, CO-80908

Site Information

Bill Price
 4512 Settlers Ranch
 Colorado Springs, CO-80908

Site & Condition


Wind: NA
 Year Built: NA
 Mitigation System: Not Installed
 SqFt: NA

Atmospheric Condition: NA
 Structure Type: NA
 Monitor Location: NA

Test Summary

Start Time: 05/07/2019 04:45
 End Time: 05/09/2019 08:45
 Measurement Interval(hr): 1.0
 Exposure Time: 2 Days 4 hrs

Overall Avg: 3.5 pCi/l
 EPA Avg: 3.6 pCi/l



***** 05/07/2019 *****

Time	Counts pCi/l	Temp F	Pressure inHg	Humidity %	Flags
05:45	1.2	60.8	22.9	40.5	
06:45	2.2	61.2	22.9	40.4	
07:45	3.8	60.8	22.9	40.6	
08:45	2.2	60.3	22.9	41.0	
09:45	3.2	59.9	22.9	41.4	
10:45	3.6	59.9	22.8	41.1	
11:45	3.2	59.9	22.8	40.9	
12:45	4.8	59.9	22.8	40.9	
13:45	4.0	60.4	22.8	41.1	
14:45	4.6	60.8	22.8	40.5	
15:45	3.4	61.5	22.8	40.1	
16:45	3.6	61.9	22.8	40.2	
17:45	4.0	61.9	22.8	40.2	
18:45	4.4	62.1	22.8	40.3	
19:45	3.6	61.9	22.8	40.5	
20:45	3.4	62.1	22.8	40.4	
21:45	3.0	61.7	22.8	40.8	
22:45	3.4	61.0	22.8	41.2	
23:45	3.0	60.3	22.7	41.5	

***** 05/08/2019 *****

Time	Counts pCi/l	Temp F	Pressure inHg	Humidity %	Flags
00:45	3.6	59.7	22.7	41.5	
01:45	3.6	59.7	22.7	41.1	
02:45	3.2	59.9	22.7	41.1	
03:45	3.2	60.3	22.7	41.2	
04:45	2.8	60.4	22.7	41.0	
05:45	2.6	60.4	22.7	40.7	
06:45	4.6	60.8	22.7	40.4	
07:45	3.2	60.3	22.7	40.5	
08:45	5.4	59.5	22.8	40.5	
09:45	1.8	59.2	22.7	40.3	
10:45	3.4	59.2	22.8	40.0	
11:45	2.2	59.0	22.8	39.6	
12:45	2.8	59.2	22.8	39.4	
13:45	4.6	59.5	22.8	39.0	
14:45	6.0	59.9	22.8	38.6	
15:45	5.0	59.7	22.8	38.4	
16:45	4.0	59.9	22.8	38.2	
17:45	3.8	59.7	22.8	38.0	
18:45	3.8	59.7	22.8	37.7	
19:45	3.6	59.5	22.9	37.4	
20:45	4.8	59.7	22.9	37.0	

***** 05/08/2019 *****

Time	Counts pCi/l	Temp F	Pressure inHg	Humidity %	Flags
21:45	4.4	59.0	22.9	36.6	
22:45	2.8	58.1	22.9	36.7	
23:45	2.4	57.9	22.9	36.3	

***** 05/09/2019 *****

Time	Counts pCi/l	Temp F	Pressure inHg	Humidity %	Flags
00:45	4.0	58.1	22.9	35.7	
01:45	4.2	58.1	22.9	35.5	
02:45	3.4	58.3	22.9	35.2	
03:45	2.8	58.3	22.9	35.2	
04:45	2.6	58.3	22.9	34.9	
05:45	4.4	58.3	22.9	34.7	
06:45	2.8	58.6	22.9	34.3	
07:45	5.5	58.8	22.9	34.4	
08:45	2.0	58.8	22.9	33.7	

Error Flags:

M Motion:

Inspector Signature _____

PC Software Version: 2.2.0

Embedded Software Version: 109