

03/20/2019 9:00AM



2.1.1 Siding, Flashing & Trim

CRACKING - MINOR



Siding showed cracking in one or more places. This is a result of temperature changes, and typical as homes with stucco age. Recommend monitoring.

2.4.1 Decks, Balconies, Porches & Steps

DECK - UNSTABLE SUPPORT



One of more areas of the deck support appears unstable. This could cause a safety hazard and further deterioration of the deck. Recommend qualified deck contractor evaluate and repair.

3.2.1 Roof Drainage Systems

DOWNSPOUTS DRAIN NEAR HOUSE



One or more downspouts drain too close to the home's foundation. This can result in excessive moisture in the soil at the foundation, which can lead to foundation/structural movement. Recommend a qualified contractor adjust downspout extensions to drain at least 6 feet from the foundation.

Here is a helpful DIY link and video on draining water flow away from your house.

3.2.2 Roof Drainage Systems

GUTTER DAMAGED



Gutters were damaged. This can result in excessive moisture in the soil at the foundation, which can lead to foundation/structural movement. Recommend a qualified contractor evaluate and repair.

Alcor Inspex Page 1 of 1