



### 5.3.1 Distribution Systems

#### **REGISTER - FLOOR REPAIR**

VARIOUS THROUGHOUT 1ST FLOOR



Items of Importance

Some registers appear serviceable in their connections to their respective floors. Recommend further evaluations and proper repairs be performed by a qualified licensed contractor, or handyman to correct and protect against potential injury to occupants due to the condition.

Recommendation

Contact a handyman or DIY project

### 8.3.2 Branch Wiring Circuits, Breakers & Fuses

#### **OPEN SPLICING**

GARAGE ATTIC



Items of Importance

Open conductor splices are present at the noted location(s) of the home. Recommend further evaluations and proper repairs be performed by qualified licensed electrical contractor to correct and protect, as needed. The installation of a junction box(es) is recommended to correct.

Recommendation

Contact a qualified electrical contractor.



### 10.2.2 Windows

#### **GLAZING DAMAGED**

2ND FLOOR SOUTH



Items of Importance

Some damage appears present to the window glazing at the noted location of the home. Recommend further evaluations and proper repairs/replacement be performed by qualified licensed glazing contractor to correct as needed.

Recommendation  
Contact a qualified window repair/installation contractor.

